

RESERVE STUDY FOR QUEENS BAY HOMEOWNERS ASSOCIATION



Management By:
Queens Bay Homeowners Association
777 Harrah Way #532
Lake Havasu, AZ 86403

Prepared By: FDReserve Studies, LLC Goodyear, AZ 85338

June 9, 2025



EXECUTIVE SUMMARY

QUEENS BAY HOMEOWNERS ASSOCIATION

June 9, 2025

Starting Reserve Balance 1/1/2026 \$780,672

Projected Fully Funded Reserve Balance 1/1/2026 \$1,669,784

Percent Fully Funded 1/1/2026 47%

Annual Reserve Contribution 2025 \$83,448

This study is based on the cash flow method of funding. This reserve analysis is based on an observation and assessment of the condition of the reserve fund based on a field assessment of the condition of the assets of the association, a projection of the useful life and remaining useful life of those assets, and the replacement costs for those assets. The general guideline used in our studies to determine whether the cost to replace or maintain an asset is paid from reserves or operations is if the replacement cost exceeds \$500 it is included in reserves. That can be modified at the direction of the Board.

Following are some key points relative to your study:

- 1. The study has a fiscal year beginning date of January 1, 2026.
- 2. The study reflects a beginning balance for the reserve fund of \$780,672 and a current annual contribution of \$83,448. The financial information was provided by the association and was not audited. As reflected by the Current Assessment Funding Model Projection in the report, on pages 1-1 and 1-2, the reserve fund is underfunded. Reserve funds are generally considered to be in a healthy condition if the reserve balance is at or above 70% of the fully funded balance.
- 3. Due to the reserve's underfunded status, the HOA Board recommends the Alternate Funding Model 2, on pages 1-3 and 1-4. The model increases the annual reserve contribution to \$175,000 in 2026 (up from \$83,448 unchanged since 2005), followed by 5% annual increases in 2027 through 2031. The Board plans on conducting a new study in 2031. Note that the study includes a 3% inflation on costs based on current construction cost indexes so some increase in funding over time is recommended to stay even with cost increase from inflation.
- 4. This study should be compared with the operating budget to make sure there are no overlaps or gaps of items in this study and in the operating budget.

- 5. The physical assessment of components was based on field reviews conducted on 3/28/2025. The field review consisted of on-site observations of common areas and facilities. No sampling or destructive testing was performed. The on-site observation is not a comprehensive quality inspection. Quantification of assets was accomplished with a combination of on-site measurements, aerial photos and information provided by the association.
- 6. The consultant has no other involvement with the association that could be considered a conflict of interest. To our knowledge, there are no material issues that have not been disclosed that would cause a distortion of the association's reserve fund.

Report was prepared by:


- William A. Schlimgen, PE, RS, APM, bill@fdreservestudies.com, 602-740-8730
- Barbie Augsburger, barbie@fdreservestudies.com, 512-633-3012.

QUEENS BAY HOMEOWNERS ASSOCIATION

Current Assessment Funding Model Summary

| Report Date | June 9, 2025 |
|---|--------------------------------------|
| Budget Year Beginning Budget Year Ending | January 1, 2026 December 31, 2026 |
| Total Units | 170 |
| | |

| Report Parameters | |
|--|-----------------------------------|
| Inflation Annual Assessment Increase Interest Rate on Reserve Deposit Tax Rate on Interest | 3.00% 0.00% 1.00% 30.00% |
| 2026 Beginning Balance | \$780,672 |



| Current Assessment Funding Model Summary of Calculations | |
|---|------------|
| Required Monthly Contribution \$40.91 per unit monthly | \$6,954.00 |
| Average Net Monthly Interest Earned | \$429.50 |
| Total Monthly Allocation to Reserves \$43.43 per unit monthly | \$7,383.50 |

QUEENS BAY HOMEOWNERS ASSOCIATION Current Assessment Funding Model Projection


Beginning Balance: \$780,672

| | | | | | Projected | Fully | |
|------|-----------|--------------|----------|--------------|------------|-----------|---------|
| | Current | Annual | Annual | Annual | Ending | Funded | Percent |
| Year | Cost | Contribution | Interest | Expenditures | Reserves | Reserves | Funded |
| | | | | | | | |
| 2026 | 2,388,936 | 83,448 | 5,154 | 91,890 | 777,384 | 1,734,341 | 45% |
| 2027 | 2,460,604 | 83,448 | 4,846 | 132,458 | 733,220 | 1,764,463 | 42% |
| 2028 | 2,534,422 | 83,448 | 3,646 | 259,249 | 561,064 | 1,668,733 | 34% |
| 2029 | 2,610,455 | 83,448 | 3,787 | 67,007 | 581,291 | 1,771,692 | 33% |
| 2030 | 2,688,768 | 83,448 | 2,799 | 227,903 | 439,635 | 1,716,700 | 26% |
| 2031 | 2,769,431 | 83,448 | 3,063 | 48,556 | 477,590 | 1,848,585 | 26% |
| 2032 | 2,852,514 | 83,448 | 2,254 | 201,819 | 361,473 | 1,831,129 | 20% |
| 2033 | 2,938,090 | 83,448 | 2,852 | 452 | 447,322 | 2,024,606 | 22% |
| 2034 | 3,026,232 | 83,448 | 2,016 | 205,354 | 327,433 | 2,017,696 | 16% |
| 2035 | 3,117,019 | 83,448 | 2,447 | 24,182 | 389,145 | 2,201,501 | 18% |
| 2036 | 3,210,530 | 83,448 | | 1,073,782 | -601,189 | 1,316,501 | |
| 2037 | 3,306,846 | 83,448 | | 88,857 | -606,598 | 1,424,072 | |
| 2038 | 3,406,051 | 83,448 | | 26,794 | -549,943 | 1,603,584 | |
| 2039 | 3,508,233 | 83,448 | | 245,595 | -712,090 | 1,568,544 | |
| 2040 | 3,613,480 | 83,448 | | 209,221 | -837,863 | 1,576,620 | |
| 2041 | 3,721,884 | 83,448 | | 93,384 | -847,799 | 1,709,766 | |
| 2042 | 3,833,541 | 83,448 | | 363,819 | -1,128,170 | 1,573,819 | |
| 2043 | 3,948,547 | 83,448 | | 607 | -1,045,330 | 1,813,526 | |
| 2044 | 4,067,003 | 83,448 | | 253,855 | -1,215,737 | 1,805,373 | |
| 2045 | 4,189,013 | 83,448 | | 59,225 | -1,191,513 | 2,003,412 | |
| 2046 | 4,314,684 | 83,448 | | 238,082 | -1,346,147 | 2,029,316 | |
| 2047 | 4,444,124 | 83,448 | | 52,708 | -1,315,407 | 2,249,910 | |
| 2048 | 4,577,448 | 83,448 | | 246,015 | -1,477,974 | 2,286,162 | |
| 2049 | 4,714,771 | 83,448 | | 191,793 | -1,586,319 | 2,386,015 | |
| 2050 | 4,856,215 | 83,448 | | 13,864 | -1,516,735 | 2,678,995 | |
| 2051 | 5,001,901 | 83,448 | | 806,230 | -2,239,517 | 2,173,566 | |
| 2052 | 5,151,958 | 83,448 | | 235,662 | -2,391,731 | 2,248,606 | |
| 2053 | 5,306,517 | 83,448 | | 77,081 | -2,385,363 | 2,496,812 | |
| 2054 | 5,465,712 | 83,448 | | 148,001 | -2,449,917 | 2,687,220 | |
| 2055 | 5,629,684 | 83,448 | | 117,552 | -2,484,021 | 2,922,742 | |

QUEENS BAY HOMEOWNERS ASSOCIATION Alternate Funding Model 2 Summary

| Report Date | June 9, 2025 |
|---|--------------------------------------|
| Budget Year Beginning Budget Year Ending | January 1, 2026 December 31, 2026 |
| Total Units | 170 |
| | |

| Report Parameters | |
|--|-----------------|
| Inflation | 3.00% |
| Interest Rate on Reserve Deposit Tax Rate on Interest | 1.00% 30.00% |
| 2026 Beginning Balance | \$780,672 |



| Alternate Funding Model 2 Summary of Calculations | | | | | | |
|---|-------------|--|--|--|--|--|
| Required Monthly Contribution | \$14,583.33 | | | | | |
| \$85.78 per unit monthly | | | | | | |
| Average Net Monthly Interest Earned | \$458.49 | | | | | |
| Total Monthly Allocation to Reserves | \$15,041.83 | | | | | |
| \$88.48 per unit monthly | | | | | | |

QUEENS BAY HOMEOWNERS ASSOCIATION Alternate Funding Model 2 Projection

Beginning Balance: \$780,672

| | | | | | Projected | Fully | |
|------|-----------|--------------|----------|--------------|-----------|-----------|---------|
| | Current | Annual | Annual | Annual | Ending | Funded | Percent |
| Year | Cost | Contribution | Interest | Expenditures | Reserves | Reserves | Funded |
| | | | | | | | |
| 2026 | 2,388,936 | 175,000 | 5,502 | 91,890 | 869,284 | 1,734,341 | 50% |
| 2027 | 2,460,604 | 183,750 | 5,873 | 132,458 | 926,449 | 1,764,463 | 53% |
| 2028 | 2,534,422 | 192,937 | 5,419 | 259,249 | 865,555 | 1,668,733 | 52% |
| 2029 | 2,610,455 | 202,584 | 6,378 | 67,007 | 1,007,510 | 1,771,692 | 57% |
| 2030 | 2,688,768 | 212,714 | 6,283 | 227,903 | 998,603 | 1,716,700 | 58% |
| 2031 | 2,769,431 | 223,349 | 7,520 | 48,556 | 1,180,917 | 1,848,585 | 64% |
| 2032 | 2,852,514 | 223,349 | 7,724 | 201,819 | 1,210,172 | 1,831,129 | 66% |
| 2033 | 2,938,090 | 223,349 | 9,344 | 452 | 1,442,413 | 2,024,606 | 71% |
| 2034 | 3,026,232 | 223,349 | 9,536 | 205,354 | 1,469,945 | 2,017,696 | 73% |
| 2035 | 3,117,019 | 223,349 | 11,002 | 24,182 | 1,680,114 | 2,201,501 | 76% |
| 2036 | 3,210,530 | 223,349 | 5,107 | 1,073,782 | 834,787 | 1,316,501 | 63% |
| 2037 | 3,306,846 | 223,349 | 6,087 | 88,857 | 975,367 | 1,424,072 | 68% |
| 2038 | 3,406,051 | 223,349 | 7,510 | 26,794 | 1,179,432 | 1,603,584 | 74% |
| 2039 | 3,508,233 | 223,349 | 7,407 | 245,595 | 1,164,593 | 1,568,544 | 74% |
| 2040 | 3,613,480 | 223,349 | 7,558 | 209,221 | 1,186,279 | 1,576,620 | 75% |
| 2041 | 3,721,884 | 223,349 | 8,524 | 93,384 | 1,324,768 | 1,709,766 | 77% |
| 2042 | 3,833,541 | 223,349 | 7,597 | 363,819 | 1,191,895 | 1,573,819 | 76% |
| 2043 | 3,948,547 | 223,349 | 9,215 | 607 | 1,423,852 | 1,813,526 | 79% |
| 2044 | 4,067,003 | 223,349 | 9,065 | 253,855 | 1,402,411 | 1,805,373 | 78% |
| 2045 | 4,189,013 | 223,349 | 10,281 | 59,225 | 1,576,817 | 2,003,412 | 79% |
| 2046 | 4,314,684 | 223,349 | 10,250 | 238,082 | 1,572,335 | 2,029,316 | 77% |
| 2047 | 4,444,124 | 223,349 | 11,520 | 52,708 | 1,754,496 | 2,249,910 | 78% |
| 2048 | 4,577,448 | 223,349 | 11,442 | 246,015 | 1,743,272 | 2,286,162 | 76% |
| 2049 | 4,714,771 | 223,349 | 11,744 | 191,793 | 1,786,572 | 2,386,015 | 75% |
| 2050 | 4,856,215 | 223,349 | 13,298 | 13,864 | 2,009,355 | 2,678,995 | 75% |
| 2051 | 5,001,901 | 223,349 | 9,298 | 806,230 | 1,435,772 | 2,173,566 | 66% |
| 2052 | 5,151,958 | 223,349 | 9,276 | 235,662 | 1,432,736 | 2,248,606 | 64% |
| 2053 | 5,306,517 | 223,349 | 10,369 | 77,081 | 1,589,374 | 2,496,812 | 64% |
| 2054 | 5,465,712 | 223,349 | 10,971 | 148,001 | 1,675,692 | 2,687,220 | 62% |
| 2055 | 5,629,684 | 223,349 | 11,791 | 117,552 | 1,793,280 | 2,922,742 | 61% |

| | .~ 0 | , official | * | | -ite | agai. | . algo | | :A & |
|--|--|---|------------|------|---|-----------------|--------------|-----|--------------|
| Description | \$.50 C. 50 | A CON 40 | CHICÉ CO S | - 58 | 4. 19. 25. 25. 25. 25. 25. 25. 25. 25. 25. 25 | ₹ 20 | ight. Englis | 070 | itis Oth Oth |
| Building Components | | | | | | | | | |
| Black Pipe - Repair/Replace | 1065 | Unfunded | | | | | | | |
| Asset ID: 1065 Restrooms - Remodel Asset ID: 1052 | 2020 | 2040 | 20,000 | 20 | 0 | 14 | 30,252 | 2 @ | 10,000.00 |
| Doors & Windows | | | | | | | | | |
| ADA Door Openers - Replace | 2015 | 2035 | 10,000 | 20 | 0 | 9 | 13,048 | 2@ | 5,000.00 |
| Asset ID: 1007 Doors & Windows - Replace Asset ID: 1009 | 1991 | 2051 | 240,000 | 50 | 10 | 25 | 502,507 | 1@ | 240,000.00 |
| Elevators | | | | | | | | | |
| Elevator (1) - Modernization Asset ID: 1054 | 1992 | 2028 | 110,600 | 35 | 1 | 2 | 117,336 | 1@ | 110,600.00 |
| Elevator (2) - Modernization | 1992 | 2030 | 110,600 | 35 | 3 | 4 | 124,481 | 1@ | 110,600.00 |
| Asset ID: 1066 Elevator (3) - Modernization | 1992 | 2032 | 110,600 | 35 | 5 | 6 | 132,062 | 1@ | 110,600.00 |
| Asset ID: 1067 Elevator (4) - Modernization | 1992 | 2034 | 110,600 | 35 | 7 | 8 | 140,105 | 1 @ | 110,600.00 |
| Asset ID: 1068 Elevator - Cab Refurbish | 1992 | 2040 | 98,000 | 35 | 13 | 14 | 148,234 | 4 @ | 24,500.00 |
| Asset ID: 1055 | | | ŕ | | | | • | | ŕ |
| Equipment-Electrical | | | | | | | | | |
| Electric Panels - Replace Asset ID: 1059 | 1991 | 2041 | 16,000 | 35 | 15 | 15 | 24,927 | 4 @ | 4,000.00 |
| Equipment-Grounds | | | | | | | | | |
| Gate Operator - Replace Asset ID: 1056 | 1992 | 2028 | 4,000 | 18 | 18 | 2 | 4,244 | 1@ | 4,000.00 |
| Irrigation Controllers - Replace Asset ID: 1061 | 2023 | 2028 | 367 | 5 | 0 | 2 | 390 | 7@ | 350.00 |
| Keypad - Replace Asset ID: 1058 | 2004 | 2028 | 1,500 | 18 | 6 | 2 | 1,591 | 1@ | 1,500.00 |
| Pressure Regulator - Replace Asset ID: 1003 | 2024 | 2030 | 5,900 | 6 | 0 | 4 | 6,641 | 1@ | 5,900.00 |
| Vacuum - Replace | 2012 | 2028 | 1,900 | 12 | 4 | 2 | 2,016 | 1@ | 1,900.00 |
| Asset ID: 1046 Vehicles & Mower - Replace Asset ID: 1053 | 2024 | 2029 | 7,500 | 5 | 0 | 3 | 8,195 | 3 @ | 5,000.00 |
| Equipment-Pool & Spa | | | | | | | | | |
| Pool Filters (A) - Replace Asset ID: 1031 | 1992 | 2026 | 2,600 | 18 | 0 | 0 | 2,600 | 1@ | 2,600.00 |

| | 98 CS TO | Post of the Manager St. | Children Cos | | -15° | dient | ingo | ڼږ | jich co ^{št} Siči |
|--|---|---|--------------|-----------------|---------------------------------------|-------|-----------|-------|-------------------------------|
| Description | 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 | Sed Ogie | Carros | \\ \S^{\varphi} | \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\ | موف | ROLL COST | Ong | jith Jain Jain |
| Equipment-Pool & Spa continued | | | | | | | | | |
| Pool Filters (B) - Replace Asset ID: 1036 | 2023 | 2041 | 2,546 | 18 | 0 | 15 | 3,967 | 1@ | 2,546.16 |
| Pool Heater - Replace Asset ID: 1035 | 2024 | 2032 | 12,000 | 8 | 0 | 6 | 14,329 | 1@ | 12,000.00 |
| Pool/Spa Pumps & Motors - Repair/ Asset ID: 1038 | 1991 | 2026 | 2,600 | 4 | 0 | 0 | 2,600 | 1@ | 10,400.00 |
| Spa Filters - Replace Asset ID: 1041 | 2023 | 2029 | 3,333 | 6 | 0 | 3 | 3,642 | 4 @ | 2,500.00 |
| Spa Heater (A) - Replace Asset ID: 1040 | 2007 | 2026 | 4,220 | 8 | 0 | 0 | 4,220 | 1@ | 4,220.00 |
| Spa Heater (B) - Replace Asset ID: 1042 | 2024 | 2032 | 4,220 | 8 | 0 | 6 | 5,039 | 1 @ | 4,220.00 |
| Fencing/Security | | | | | | | | | |
| Metal Fence - Repairs Asset ID: 1024 | 2005 | 2026 | 5,500 | 5 | 0 | 0 | 5,500 | 1@ | 5,500.00 |
| Security System - Refurbish/Replace Asset ID: 1001 | 2024 | 2030 | 11,500 | 6 | 0 | 4 | 12,943 | 1@ | 11,500.00 |
| Fire Protection System | | | | | | | | | |
| Backflow Preventers - Replace Asset ID: 1002 | 2024 | 2044 | 6,825 | 20 | 0 | 18 | 11,619 | 1@ | 6,825.00 |
| Check Valves & Fire Connections - R Asset ID: 1064 | 2025 | 2045 | 975 | 20 | 0 | 19 | 1,710 | 1@ | 975.00 |
| Fire Protection Components - Repla Asset ID: 1004 | 2023 | 2048 | 43,000 | 25 | 0 | 22 | 82,392 | 1@ | 43,000.00 |
| Sprinkler Heads - Test Asset ID: 1005 | 1005 | Unfunded | | | | | | | |
| Flooring | | | | | | | | | |
| Flooring Carpet Hallways - Replace Asset ID: 1048 | 2025 | 2037 | 34,200 | 12 | 0 | 11 | 47,341 | 1@ | 34,200.00 |
| Flooring Carpet Lobby - Replace Asset ID: 1047 | 2025 | 2037 | 4,992 | 12 | 0 | 11 | 6,910 | 1600@ | 3.12 |
| Furnishings-Interior | | | | | | | | | |
| Lobby Furnishings - Replace Asset ID: 1051 | 2004 | 2030 | 37,206 | 18 | 8 | 4 | 41,876 | 1@ | 37,205.89 |
| Roll Down Shades - Replace Asset ID: 1006 | 1991 | 2051 | 20,000 | 50 | 10 | 25 | 41,876 | 1 @ | 20,000.00 |
| Furnishings-Pool & Patio | | | | | | | | | |
| Patio Furnishings - Replace Asset ID: 1028 | 2018 | 2028 | 12,000 | 10 | 0 | 2 | 12,731 | 1 @ | 12,000.00 |

| | Q ⁶ S ⁶ S | Poleconen | CHI CO | | | Strent | ingo Spingo | , Out | |
|--|---------------------------------|-----------|--------|----|----|--------|----------------|---------|-----------|
| Description | <i>ర్మ</i> స్ట | 40,00 | 0,0 | క | Ø, | Ø, | , Kg, Co, | Q, | Str |
| Furnishings-Pool & Patio contin | | | | | | | | | |
| Patio Grills - Replace Asset ID: 1033 | 2024 | 2032 | 2,200 | 8 | 0 | 6 | 2,627 | 2 @ | 1,100.00 |
| Pool Furnishings - Replace Asset ID: 1037 | 2019 | 2029 | 20,000 | 10 | 0 | 3 | 21,855 | 1 @ | 20,000.00 |
| Pool Furnishings - Restrap Asset ID: 1062 | 2024 | 2034 | 6,700 | 10 | 0 | 8 | 8,487 | 1 @ | 6,700.00 |
| Grounds Components | | | | | | | | | |
| Fountain - Refurbish/Replacement P Asset ID: 1027 | 2025 | 2032 | 10,000 | 7 | 0 | 6 | 11,941 | 1@ | 10,000.00 |
| Guard Shack - Refurbish Asset ID: 1057 | 1057 | Unfunded | | | | | | | |
| HVAC | | | | | | | | | |
| HVAC Elevators - Replace Asset ID: 1012 | 2010 | 2028 | 8,000 | 18 | 0 | 2 | 8,487 | 2 @ | 4,000.00 |
| HVAC Hallways - Replace Asset ID: 1010 | 2006 | 2028 | 11,000 | 18 | 4 | 2 | 11,670 | 2 @ | 5,500.00 |
| HVAC Lobby - Replace Asset ID: 1011 | 2009 | 2027 | 16,600 | 18 | 0 | 1 | 17,098 | 2 @ | 8,300.00 |
| Lighting | | | | | | | | | |
| Bollard Lights - Replace Asset ID: 1025 | 1992 | 2032 | 9,000 | 25 | 15 | 6 | 10,746 | 6@ | 1,500.00 |
| Light Fixtures - Replace Asset ID: 1026 | 2022 | 2052 | 8,550 | 30 | 0 | 26 | 18,439 | 19 @ | 450.00 |
| Painting | | | | | | | | | |
| Carport Structure - Paint Asset ID: 1018 | 2003 | 2027 | 25,000 | 10 | 14 | 1 | 25,750 | 1@ | 25,000.00 |
| Interior Lobby Ceiling - Paint Asset ID: 1063 | 2025 | 2035 | 5,200 | 10 | 0 | 9 | 6,785 | 1@ | 5,200.00 |
| Metal Components- Paint Asset ID: 1019 | 2003 | 2026 | 65,000 | 10 | 0 | 0 | 65,000 | 1@ | 65,000.00 |
| Stucco Trim - Paint Asset ID: 1021 | 2021 | 2031 | 32,560 | 10 | 0 | 5 | 37,746 | 29600@ | 1.10 |
| Stucco Walls - Paint Asset ID: 1020 | 1999 | 2026 | 11,970 | 10 | 0 | 0 | 11,970 | 11970 @ | 1.00 |
| Recreation/Pool | | | | | | | | | |
| Patio Deck - Recoat Asset ID: 1029 | 2024 | 2031 | 3,825 | 7 | 0 | 5 | 4,434 | 1530 @ | 2.50 |
| Patio Deck - Resurface Asset ID: 1030 | 2024 | 2045 | 11,000 | 21 | 0 | 19 | 19,289 | 1 @ | 11,000.00 |

| | 78 . 25 ric | S A CONTRACTOR OF THE SECOND S | Category Cost | | | dusir Sasar | idigis | , , , , , , | پوت ^ا رون ^خ ایرنت |
|---|-------------|--|---------------|----|----|----------------|--------------|----------------|--|
| Description | Dy copy | 500 Oug | Car. Co. | 5 | A. | Q. | igiti çalibê | Ogia o | The |
| Recreation/Pool continued | | | | | | | | | |
| Pool - Resurface Asset ID: 1039 | 2005 | 2030 | 25,683 | 25 | 0 | 4 | 28,906 | 1@ | 25,682.90 |
| Pool Deck - Recoat Asset ID: 1044 | 2025 | 2039 | 12,250 | 7 | 0 | 13 | 17,990 | 3500 @ | 3.50 |
| Pool Deck - Resurface Asset ID: 1045 | 2011 | 2032 | 21,000 | 21 | 0 | 6 | 25,075 | 3500 @ | 6.00 |
| Spa - Resurface Asset ID: 1043 | 2005 | 2030 | 9,000 | 25 | 0 | 4 | 10,130 | 1@ | 9,000.00 |
| Roofing | | | | | | | | | |
| Carport Roofs - Replace Asset ID: 1017 | 1017 | Unfunded | | | | | | | |
| Roofs - Repair/Replace Asset ID: 1016 | 2012 | 2042 | 202,500 | 30 | 0 | 16 | 324,953 | 45000 @ | 4.50 |
| Streets/Asphalt | | | | | | | | | |
| Asphalt - Crack Seal & Seal Coat Asset ID: 1015 | 2024 | 2029 | 30,488 | 5 | 0 | 3 | 33,315 | 1@ | 30,488.00 |
| Asphalt - Remove & Replace Asset ID: 1013 | 1991 | 2036 | 604,125 | 40 | 5 | 10 | 811,893 | 161100 @ | 3.75 |
| Asphalt - Slurry Seal Asset ID: 1014 | 2020 | 2028 | 95,000 | 8 | 0 | 2 | 100,785 | 1@ | 95,000.00 |
| Tree Trimming | | | | | | | | | |
| Flooring Carpet Outdoor - Replace Asset ID: 1049 | 2014 | 2027 | 87,000 | 12 | 1 | 1 | 89,610 | 1@ | 87,000.00 |

Black Pipe - Repair/Replace

| | Asset Actual Cost | 1065 | Asset ID |
|------|---------------------|----------------------------|-------------------|
| 100% | Percent Replacement | Buildings | |
| | Future Cost | Building Components | Category |
| | | January 1991 | Placed in Service |
| | | • | No Useful Life |

Budget for black pipe repair/replace. Repairs made as units are remodeled.

Restrooms - Remodel

| estrooms - Kemou | .61 | 2 EA | (a) \$10,000.00 |
|-------------------|----------------------------|---------------------|-----------------|
| Asset ID | 1052 | Asset Actual Cost | \$20,000.00 |
| | Buildings | Percent Replacement | 100% |
| Category | Building Components | Future Cost | \$30,251.79 |
| Placed in Service | January 2020 | | |
| Useful Life | 20 | | |
| Replacement Year | 2040 | | |
| Remaining Life | 14 | | |
| | | | |



Good condition. Budget to remodel (2) restrooms. One located inside lobby and one on the patio.

ADA Door Openers - Replace

| 1007 | Asset A |
|-----------------|--|
| Buildings | Percent Re |
| Doors & Windows | F |
| January 2015 | |
| 20 | |
| 2035 | |
| 9 | |
| | Buildings Doors & Windows January 2015 20 |

2 EA @ \$5,000.00 Actual Cost \$10,000.00 eplacement 100% Future Cost \$13,047.73



Working condition. Budget to replace ADA automatic door openers.

Doors & Windows - Replace

Remaining Life

| oors & Windows - | Replace | 1 LS | @ \$240,000.00 |
|-------------------|-----------------|---------------------|----------------|
| Asset ID | 1009 | Asset Actual Cost | \$240,000.00 |
| | Buildings | Percent Replacement | 100% |
| Category | Doors & Windows | Future Cost | \$502,506.70 |
| Placed in Service | January 1991 | | |
| Useful Life | 50 | | |
| Adjustment | 10 | | |
| Replacement Year | 2051 | | |

25





The large aluminum frame window walls on either side of the lobby should last many years.

Doors & Windows - Replace continued...

We estimate there is approximately 3,500 to 4,000 sf of window wall including doors. Appears to be in good condition.

| Elevator (1) - Moder | nization | 1 EA | @ \$110,600.00 |
|----------------------|--------------|---------------------|----------------|
| Asset ID | 1054 | Asset Actual Cost | \$110,600.00 |
| | Buildings | Percent Replacement | 100% |
| Category | Elevators | Future Cost | \$117,335.54 |
| Placed in Service | January 1992 | | |
| Useful Life | 35 | | |
| Adjustment | 1 | | |
| Replacement Year | 2028 | | |
| Remaining Life | 2 | | |



Working condition. Budget to modernize elevator equipment including but not limited to: controller, fixtures, hydrolic pump and components.

2025 - Otis bid on one elevator out of four for moderization of all equipment total \$110,600 each elevator.

2025 - TK Elevator bid on one elevator out of our for moderization of all equipment total \$161,460.

| Elevator (2) - Modern | ization | 1.77 | Φ110 600 00 |
|-----------------------|--------------|---------------------|----------------|
| Lievator (2) - Wodern | | 1 EA | @ \$110,600.00 |
| Asset ID | 1066 | Asset Actual Cost | \$110,600.00 |
| | Buildings | Percent Replacement | 100% |
| Category | Elevators | Future Cost | \$124,481.27 |
| Placed in Service | January 1992 | | |
| Useful Life | 35 | | |
| Adjustment | 3 | | |
| Replacement Year | 2030 | | |
| Remaining Life | 4 | | |

Elevator (2) - Modernization continued...



Working condition. Budget to modernize elevator equipment including but not limited to: controller, fixtures, hydrolic pump and components.

2025 - Otis bid on one elevator out of four for moderization of all equipment total \$110,600 each elevator.

2025 - TK Elevator bid on one elevator out of our for moderization of all equipment total \$161,460.

| Elevator (3) - Moderniz | zation | 1 EA | @ \$110,600.00 |
|-------------------------|--------------|---------------------|----------------|
| Asset ID | 1067 | Asset Actual Cost | \$110,600.00 |
| | Buildings | Percent Replacement | 100% |
| Category | Elevators | Future Cost | \$132,062.18 |
| Placed in Service | January 1992 | | |
| Useful Life | 35 | | |
| Adjustment | 5 | | |
| Replacement Year | 2032 | | |
| Remaining Life | 6 | | |



Working condition. Budget to modernize elevator equipment including but not limited to: controller, fixtures, hydrolic pump and components.

Elevator (3) - Modernization continued...

2025 - Otis bid on one elevator out of four for moderization of all equipment total \$110,600 each elevator.

2025 - TK Elevator bid on one elevator out of our for moderization of all equipment total \$161,460.

| Elevator (4) - Moderniz | ation | 1 EA | @ \$110,600.00 |
|-------------------------|--------------|---------------------|----------------|
| Asset ID | 1068 | Asset Actual Cost | \$110,600.00 |
| | Buildings | Percent Replacement | 100% |
| Category | Elevators | Future Cost | \$140,104.77 |
| Placed in Service | January 1992 | | |
| Useful Life | 35 | | |
| Adjustment | 7 | | |
| Replacement Year | 2034 | | |
| Remaining Life | 8 | | |



Working condition. Budget to modernize elevator equipment including but not limited to: controller, fixtures, hydrolic pump and components.

2025 - Otis bid on one elevator out of four for moderization of all equipment total \$110,600 each elevator.

2025 - TK Elevator bid on one elevator out of our for moderization of all equipment total \$161,460.

| Elevator - Cab Refurbish | | 4 EA | @ \$24,500.00 |
|--------------------------|--------------|---------------------|---------------|
| Asset ID | 1055 | Asset Actual Cost | \$98,000.00 |
| | Buildings | Percent Replacement | 100% |
| Category | Elevators | Future Cost | \$148,233.79 |
| Placed in Service | January 1992 | | |
| Useful Life | 35 | | |
| Adjustment | 13 | | |
| Replacement Year | 2040 | | |
| Remaining Life | 14 | | |



Budget to refurbish the interiors of the four elevators.

2025 - Otis bid on one cab interior refurbish out of the four total \$20,000 each.

2025 - TKE bid on one cab interior refurbish out of the four total \$24,500 each.

| Electric Panels - Re | place | 4 EA | @ \$4,000.00 |
|----------------------|----------------------|---------------------|--------------|
| Asset ID | 1059 | Asset Actual Cost | \$16,000.00 |
| | Buildings | Percent Replacement | 100% |
| Category | Equipment-Electrical | Future Cost | \$24,927.48 |
| Placed in Service | January 1991 | | |
| Useful Life | 35 | | |
| Adjustment | 15 | | |
| Replacement Year | 2041 | | |
| Remaining Life | 15 | | |



Working condition. Budget to replace (4) 400 amp breaker boxes in equipment rooms.

| Gate Operator - Repl | ace | 1 EA | @ \$4,000.00 |
|----------------------|--------------------------|---------------------|--------------|
| Asset ID | 1056 | Asset Actual Cost | \$4,000.00 |
| | Grounds | Percent Replacement | 100% |
| Category | Equipment-Grounds | Future Cost | \$4,243.60 |

Placed in Service January 1992
Useful Life 18
Adjustment 18
Replacement Year 2028
Remaining Life 2



Working condition. Budget to replace Door King, model 910, sliding gate operator.

| T | D 1 | | |
|-----------------------|--------------------------|---------------------|------------|
| Irrigation Controller | s - Replace | 7 EA | @ \$350.00 |
| Asset ID | 1061 | Asset Actual Cost | \$367.50 |
| | Grounds | Percent Replacement | 15% |
| Category | Equipment-Grounds | Future Cost | \$389.88 |
| Placed in Service | January 2023 | | |
| Useful Life | 5 | | |
| Replacement Year | 2028 | | |
| Remaining Life | 2 | | |



Working condition. Budget to replace (7) assume 6-station wall mounted irrigation controllers

Irrigation Controllers - Replace continued...

when needed. Various ages.

| (Keypad - Replace) | | 1 EA | @ \$1,500.00 |
|--------------------|--------------------------|---------------------|--------------|
| Asset ID | 1058 | Asset Actual Cost | \$1,500.00 |
| | Grounds | Percent Replacement | 100% |
| Category | Equipment-Grounds | Future Cost | \$1,591.35 |
| Placed in Service | January 2004 | | |
| Useful Life | 18 | | |
| Adjustment | 6 | | |
| Replacement Year | 2028 | | |
| Remaining Life | 2 | | |



Working condition. Budget to replace Linear keypad at entrance.

| Pressure Regulator - | Replace | 1 LS | @ \$5,900.00 |
|----------------------|--------------------------|---------------------|--------------|
| Asset ID | 1003 | Asset Actual Cost | \$5,900.00 |
| | Grounds | Percent Replacement | 100% |
| Category | Equipment-Grounds | Future Cost | \$6,640.50 |
| Placed in Service | January 2024 | | |
| Useful Life | 6 | | |
| Replacement Year | 2030 | | |
| Remaining Life | 4 | | |

Pressure Regulator - Replace continued...



Budget to replace pressure regulator.

| |) | | |
|-------------------|--------------------------|---------------------|--------------|
| Vacuum - Replace | | 1 EA | @ \$1,900.00 |
| Asset ID | 1046 | Asset Actual Cost | \$1,900.00 |
| | Grounds | Percent Replacement | 100% |
| Category | Equipment-Grounds | Future Cost | \$2,015.71 |
| Placed in Service | January 2012 | | |
| Useful Life | 12 | | |
| Adjustment | 4 | | |
| Replacement Year | 2028 | | |
| Remaining Life | 2 | | |



Old condition. Budget to replace vacuum located at the boat/car wash area.

| Vehicles & Mower - | Replace | 3 EA | @ \$5,000.00 |
|--------------------|--------------------------|---------------------|--------------|
| Asset ID | 1053 | Asset Actual Cost | \$7,500.00 |
| | Grounds | Percent Replacement | 50% |
| Category | Equipment-Grounds | Future Cost | \$8,195.45 |
| Placed in Service | January 2024 | | |
| Useful Life | 5 | | |
| Replacement Year | 2029 | | |
| Remaining Life | 3 | | |



Budget on a 5 year recurring cycle to replace (1) newer cart, (1) older cart and (1) D130 riding lawn mower.

1 EA

@ \$2,600.00

\$2,600.00 100%

\$2,600.00

Pool Filters (A) - Replace

Asset ID 1031 Asset Actual Cost Recreation/Pool Percent Replacement Category Equipment-Pool & Spa **Future Cost** Placed in Service January 1992 Useful Life 18 Replacement Year 2026 Remaining Life 0



Working condition. (1) old filter & (1) new filter.

Pool Filters (B) - Replace

Replacement Year Remaining Life

1 EA @ \$2,546.16 Asset ID 1036 Asset Actual Cost \$2,546.16 Recreation/Pool Percent Replacement 100% Category Equipment-Pool & Spa **Future Cost** \$3,966.83 Placed in Service January 2023 Useful Life 18



2041

15

Working condition. (1) old filter & (1) new filter.

Pool Heater - Replace

| ol Heater - Replace | | 1 EA | @ \$12,000.00 |
|---------------------|-------------------|---------------------|---------------|
| Asset ID | 1035 | Asset Actual Cost | \$12,000.00 |
| | Recreation/Pool | Percent Replacement | 100% |
| CategoryEqu | ipment-Pool & Spa | Future Cost | \$14,328.63 |
| Placed in Service | June 2024 | | |
| Useful Life | 8 | | |
| Replacement Year | 2032 | | |
| Remaining Life | 6 | | |



Working condition. Budget to replace Pentair ETI-400 ASME gas heater. 2024 - Robert Starkey installed 400K gas heater total \$11,510.

Pool/Spa Pumps & Motors - Repair/Replace

| Asset ID Category Equ | 1038 Recreation/Pool ipment-Pool & Spa | 1 LS Asset Actual Cost Percent Replacement Future Cost | @ \$10,400.00 \$2,600.00 25% \$2,600.00 |
|---|--|--|--|
| Placed in Service Useful Life Replacement Year Remaining Life | January 1991 4 2026 0 | | |

Pool/Spa Pumps & Motors - Repair/Replace continued...



Working condition. Component provides a budget to repair and/or replace (2) 1 HP @ \$1000 each, (2) 2 HP @ \$1,200 each and (2) 3 HP @ \$3,000 each every four years. Various ages.

| Spa Filters | - Replace |
|-------------|-----------|
| | |

Replacement Year

Remaining Life

4 EA @ \$2,500.00 1041 Asset Actual Cost \$3,333.33 Asset ID Recreation/Pool Percent Replacement 33.33% Category Equipment-Pool & Spa **Future Cost** \$3,642.42 Placed in Service January 2023 Useful Life

2029

3



Working condition. Budget to replace (1) Pentair PCC 106 yr 2024, (2) CCP520 yr 2022 and (1) CCP520 old.

2023 - Robert Starkey installed Clean Clear Plus 520 total \$2,327.

@ \$4,220.00

\$4,220.00

\$4,220.00

100%

Spa Heater (A) - Replace

1 EA Asset ID 1040 Asset Actual Cost Recreation/Pool Percent Replacement Category Equipment-Pool & Spa **Future Cost** Placed in Service January 2007 Useful Life Replacement Year 2026 Remaining Life 0



Working condition. Budget to replace West Spa Jacuzzi JXN-26Y.

Spa Heater (B) - Replace

Replacement Year

Remaining Life

1 EA @ \$4,220.00 Asset ID 1042 Asset Actual Cost \$4,220.00 Recreation/Pool Percent Replacement 100% Category Equipment-Pool & Spa **Future Cost** \$5,038.90 Placed in Service January 2024 Useful Life

2032

6



Working condition. Budget to replace the Pentair gas heater.

Metal Fence - Repairs

Asset ID 1024 As
Recreation/Pool Perce
Category Fencing/Security
Placed in Service January 2005
Useful Life 5
Replacement Year 2026
Remaining Life 0

1 LS @ \$5,500.00
Asset Actual Cost \$5,500.00
Percent Replacement 100%
Future Cost \$5,500.00





Budget to repair metal fencing. Noted approximately (5) sections/places where in need of repair due to spray irrigation, rusting.

Security System - Refurbish/Replace

Asset ID 1001
Buildings
Category Fencing/Security
Placed in Service June 2024
Useful Life 6
Replacement Year 2030
Remaining Life 4

1 LS @ \$11,500.00
Asset Actual Cost \$11,500.00
Percent Replacement 100%
Future Cost \$12,943.35



Budget to refurbish and/or replace security system including but not limited to: cameras,

Security System - Refurbish/Replace continued...

wiring, NVR, etc.

2024 - Coram installed (2) 24 channel NVR, (1) 16 channel NVR and (55) video feed license cameras total \$11,500.

Backflow Preventers - Replace

| ckflow Preventers - Replace | | 1 LS | @ \$6,825.00 | |
|---------------------------------|--------------|---------------------|--------------|--|
| Asset ID | 1002 | Asset Actual Cost | \$6,825.00 | |
| | Grounds | Percent Replacement | 100% | |
| Category Fire Protection System | | Future Cost | \$11,619.10 | |
| Placed in Service | January 2024 | | | |
| Useful Life | 20 | | | |
| Replacement Year | 2044 | | | |
| Remaining Life | 18 | | | |
| | | | | |



Budget to replace (1) 3" backflow @ \$5,200 and (1) 2" @ \$1,625. Placed in service date based on useful life and commuity age.

3" BFP replaced in 2024 for \$5,168.

Check Valves & Fire Connections - Replace

| | | 1 LS | @ \$975.00 |
|-------------------|-------------------|---------------------|------------|
| Asset ID | 1064 | Asset Actual Cost | \$975.00 |
| | Grounds | Percent Replacement | 100% |
| Category Fire | Protection System | Future Cost | \$1,709.67 |
| Placed in Service | March 2025 | | |
| Useful Life | 20 | | |
| Replacement Year | 2045 | | |
| Remaining Life | 19 | | |

Check Valves & Fire Connections - Replace continued...



Budget to replace (2) 4" check valves & (2) 4x2 - 1/2" fire dept connections.

2025 - Pipecraft replace (2) 4" check valves & (2) $4x^2 - 1/2$ " fire dept connections total \$973.25.

| Fire Protection | Components | - Replace |
|-----------------|------------|-----------|
| | | |

Asset ID 1004
Buildings
Category Fire Protection System
Placed in Service January 2023
Useful Life 25
Replacement Year 2048
Remaining Life 22





Budget to replace fire control system including monitor panel and other detector and alarm systems.

Monitor system equipment replaced/upgraded in 2023 by Western Alarm for \$40,800

Sprinkler Heads - Test

| | Asset Actual Cost | 1005 | Asset ID |
|------|---------------------|-------------------|-------------------|
| 100% | Percent Replacement | Buildings | |
| | Future Cost | Protection System | Category Fire |
| | | January 2015 | Placed in Service |
| | | 20 | Useful Life |
| | | 2035 | Replacement Year |
| | | 9 | Remaining Life |
| | | | |



Sprinkler heads should be tested per NFPA 25. There are different types of sprinkler heads. When they should be tested depends on the type of head. Recommend Association consult with their fire protection vendor to determine if and when testing should be done.

Flooring Carpet Hallways - Replace

Asset ID 1048 Asset I
Buildings Percent R
Category Flooring
Placed in Service January 2025
Useful Life 12
Replacement Year 2037
Remaining Life 11

Asset Actual Cost \$34,200.00
Percent Replacement 100%
Future Cost \$47,340.80

1 LS

@ \$34,200.00



Will be replaced in 2025.

Flooring Carpet Lobby - Replace

Asset ID 1047
Buildings
Category Flooring
Placed in Service January 2025
Useful Life 12
Replacement Year 2037
Remaining Life 11

 1,600 SF
 @ \$3.12

 Asset Actual Cost
 \$4,992.00

 Percent Replacement
 100%

 Future Cost
 \$6,910.09



New condition. Budget to replace commercial grade carpet in the lobby.

Flooring Carpet Lobby - Replace continued...

2025 - Rug Hut installed new lobby carpet total \$4,995.

Lobby Furnishings - Replace

| Replace | 1 LS | @ \$37,205.89 |
|----------------------|--|---|
| 1051 | Asset Actual Cost | \$37,205.89 |
| Buildings | Percent Replacement | 100% |
| Furnishings-Interior | Future Cost | \$41,875.56 |
| January 2004 | | |
| 18 | | |
| 8 | | |
| 2030 | | |
| 4 | | |
| | 1051 Buildings Furnishings-Interior January 2004 18 8 2030 | 1051 Asset Actual Cost Buildings Percent Replacement Furnishings-Interior January 2004 18 8 2030 |



Good condition. Budget to replace lobby furnishings including but not limited to: chiars, tables, couches, artwork, etc.

Roll Down Shades - Replace

| oll Down Shades - Replace | | 1 LS | @ \$20,000.00 |
|---------------------------|----------------------|---------------------|---------------|
| Asset ID | 1006 | Asset Actual Cost | \$20,000.00 |
| | Buildings | Percent Replacement | 100% |
| Category | Furnishings-Interior | Future Cost | \$41,875.56 |
| Placed in Service | January 1991 | | |
| Useful Life | 50 | | |
| Adjustment | 10 | | |
| Replacement Year | 2051 | | |
| Remaining Life | 25 | | |
| | | | |

Roll Down Shades - Replace continued...



Long life. Motorized roll-up sun shades. Appear to be in good condition. Assume shades were installed when building was constructed.

| Patio 1 | Furnis | hings - | - Repl | lace |
|---------|--------|---------|--------|------|
| | | | | |

1 LS @ \$12,000.00 Asset ID 1028 Asset Actual Cost \$12,000.00 Recreation/Pool 100% Percent Replacement \$12,730.80 Catego Furnishings-Pool & Patio **Future Cost**

Placed in Service January 2018 Useful Life 10 Replacement Year 2028 Remaining Life 2



Good condition. Budget to replace (6) glass metal tables with (4) cushioned metal chairs each, (6) umbrellas and (2) metal tables with (4) cushioned chairs each. Placed in service date unknown based on condition.

2032

6

|--|

Replacement Year Remaining Life

| Asset ID | 1033 | Asset Actual Cost | \$2,200.00 |
|-------------------|--------------------|---------------------|------------|
| | Recreation/Pool | Percent Replacement | 100% |
| Catego Fyurnis | hings-Pool & Patio | Future Cost | \$2,626.91 |
| Placed in Service | January 2024 | | |
| Useful Life | 8 | | |

2 EA

@ \$1,100.00


Patio Grills - Replace continued...



Working condition. Budget to replace stand alone propane BBQ grills.

Pool Furnishings - Replace


| ol Furnishings - Rep | place | 1 LS | @ \$20,000.00 |
|----------------------|---------------------|---------------------|---------------|
| Asset ID | 1037 | Asset Actual Cost | \$20,000.00 |
| | Recreation/Pool | Percent Replacement | 100% |
| Catego Fyurnis | shings-Pool & Patio | Future Cost | \$21,854.54 |
| Placed in Service | January 2019 | | |
| Useful Life | 10 | | |
| Replacement Year | 2029 | | |
| Remaining Life | 3 | | |
| | | | |



Good condition. Budget to replace (30) strap lounge chairs, (4) composite tables with (4) strap chairs each and (4) umbrellas.

| Pool | Furni | shings | - Restrap |
|------|-------|--------|-----------|
| | | | |

| or runnshings - Ke | Strap | 1 LS | (a) \$6,700.00 |
|-----------------------|---------------------|---------------------|----------------|
| Asset ID | 1062 | Asset Actual Cost | \$6,700.00 |
| | Recreation/Pool | Percent Replacement | 100% |
| Catego Fy urni | shings-Pool & Patio | Future Cost | \$8,487.36 |
| Placed in Service | September 2024 | | |
| Useful Life | 10 | | |
| Replacement Year | 2034 | | |
| Remaining Life | 8 | | |



Good condition. Budget to replace (30) strap lounge chairs, (4) composite tables with (4) strap chairs each and (4) umbrellas.

2024 - Seabreeze Patio restrap (30) loungers and (16) chairs total \$6,434.

1 LS

@ \$10,000.00

\$10,000.00 100%

\$11,940.52

Fountain - Refurbish/Replacement Parts

Asset ID 1027 Asset Actual Cost
Grounds Percent Replacement
Category Grounds Components Future Cost
Placed in Service January 2025
Useful Life 7
Replacement Year 2032
Remaining Life 6



Working condition. Refurbished in 2025.

Guard Shack - Refurbish

Asset ID 1057 Asset Actual Cost
Grounds Percent Replacement 100%
Category Grounds Components Future Cost

Placed in Service January 1991
No Useful Life



Unfunded. Not in use. No anticipation to refurbish.

| HVAC Elevators - Repla | ice | 2 EA | @ \$4,000.00 |
|------------------------|--------------|---------------------|--------------|
| Asset ID | 1012 | Asset Actual Cost | \$8,000.00 |
| | Buildings | Percent Replacement | 100% |
| Category | HVAC | Future Cost | \$8,487.20 |
| Placed in Service | January 2010 | | |
| Useful Life | 18 | | |
| Replacement Year | 2028 | | |
| Remaining Life | 2 | | |



Working condition. Budget to remove and install (2) small HVAC units for elevators. Date in service unknown.

| HVAC Hallways - Repla | ce | 2 EA | @ \$5,500.00 |
|-----------------------|--------------|---------------------|--------------|
| Asset ID | 1010 | Asset Actual Cost | \$11,000.00 |
| | Buildings | Percent Replacement | 100% |
| Category | HVAC | Future Cost | \$11,669.90 |
| Placed in Service | January 2006 | | |
| Useful Life | 18 | | |
| Adjustment | 4 | | |
| Replacement Year | 2028 | | |
| Remaining Life | 2 | | |

HVAC Hallways - Replace continued...



Working older condition. Budget to remove and install (assume 2.5 ton) HVAC units on roof.

| HVAC Lobby - Replace | | 2 EA | @ \$8,300.00 |
|----------------------|--------------|---------------------|--------------|
| Asset ID | 1011 | Asset Actual Cost | \$16,600.00 |
| | Buildings | Percent Replacement | 100% |
| Category | HVAC | Future Cost | \$17,098.00 |
| Placed in Service | January 2009 | | |
| Useful Life | 18 | | |
| Replacement Year | 2027 | | |
| Remaining Life | 1 | | |



Working condition. Budget to remove and install (assume 4.0 ton) HVAC units on roof. Date in service unknown.

| Bollard Lights - Replace | | 6 EA | @ \$1,500.00 |
|--------------------------|--------------|---------------------|--------------|
| Asset ID | 1025 | Asset Actual Cost | \$9,000.00 |
| | Grounds | Percent Replacement | 100% |
| Category | Lighting | Future Cost | \$10,746.47 |
| Placed in Service | January 1992 | | |
| Useful Life | 25 | | |
| Adjustment | 15 | | |
| Replacement Year | 2032 | | |
| Remaining Life | 6 | | |



Working condition. Budget to replace 42" metal bollard light fixtures located in from of main entrance.

| Light Fixtures - Replace | | 19 EA | @ \$450.00 |
|--------------------------|--------------|---------------------|-------------|
| Asset ID | 1026 | Asset Actual Cost | \$8,550.00 |
| | Grounds | Percent Replacement | 100% |
| Category | Lighting | Future Cost | \$18,438.85 |
| Placed in Service | January 2022 | | |
| Useful Life | 30 | | |
| Replacement Year | 2052 | | |
| Remaining Life | 26 | | |

Light Fixtures - Replace continued...



Working condition. Budget to replace (4) double and (11) single light fixtures.

| Carport Structure - Paint | | 1 LS | @ \$25,000.00 |
|---------------------------|--------------|---------------------|---------------|
| Asset ID | 1018 | Asset Actual Cost | \$25,000.00 |
| | Grounds | Percent Replacement | 100% |
| Category | Painting | Future Cost | \$25,750.00 |
| Placed in Service | January 2003 | | |
| Useful Life | 10 | | |
| Adjustment | 14 | | |
| Replacement Year | 2027 | | |
| Remaining Life | 1 | | |



Fair to poor condition. Budget to repaint carport structures.

| Interior Lobby Ceiling - | Paint | 1 LS | @ \$5,200.00 |
|--------------------------|--------------|---------------------|--------------|
| Asset ID | 1063 | Asset Actual Cost | \$5,200.00 |
| | Buildings | Percent Replacement | 100% |
| Category | Painting | Future Cost | \$6,784.82 |
| Placed in Service | January 2025 | | |
| Useful Life | 10 | | |
| Replacement Year | 2035 | | |
| Remaining Life | 9 | | |



Good condition. Budget to repaint lobby ceiling.

Interior Lobby Ceiling - Paint continued...

2025 - Curb Appeal painted lobby ceiling total \$5,185.

| Metal Components- Paint | | 1 LS | @ \$65,000.00 |
|-------------------------|--------------|---------------------|---------------|
| Asset ID | 1019 | Asset Actual Cost | \$65,000.00 |
| | Buildings | Percent Replacement | 100% |
| Category | Painting | Future Cost | \$65,000.00 |
| Placed in Service | January 2003 | | |
| Useful Life | 10 | | |
| Replacement Year | 2026 | | |
| Remaining Life | 0 | | |





Poor condition. Budget to paint doors, metal stair railings, metal on balconies, and all other metal components on buildings and at pool.

| Stucco Trim - Paint | | 29,600 SF | @ \$1.10 |
|---------------------|--------------|---------------------|-------------|
| Asset ID | 1021 | Asset Actual Cost | \$32,560.00 |
| | Buildings | Percent Replacement | 100% |
| Category | Painting | Future Cost | \$37,745.96 |
| Placed in Service | January 2021 | | |
| Useful Life | 10 | | |
| Replacement Year | 2031 | | |
| Remaining Life | 5 | | |

Stucco Trim - Paint continued...



Fair to good condition. Budget to paint trim around the top fo the building, the over hang at the front and rear enterance and the turetts.

| Stucco Walls - Paint | | 11,970 SF | @ \$1.00 |
|----------------------|--------------|---------------------|-------------|
| Asset ID | 1020 | Asset Actual Cost | \$11,970.00 |
| | Buildings | Percent Replacement | 100% |
| Category | Painting | Future Cost | \$11,970.00 |
| Placed in Service | January 1999 | | |
| Useful Life | 10 | | |
| Replacement Year | 2026 | | |
| Remaining Life | 0 | | |



Poor condition. Budget to paint the perimeter stucco walls. Noted chipped, fades and in need of paint.

| Patio Deck - Recoat | | 1,530 SF | @ \$2.50 |
|---------------------|-----------------|---------------------|------------|
| Asset ID | 1029 | Asset Actual Cost | \$3,825.00 |
| | Recreation/Pool | Percent Replacement | 100% |
| Category | Recreation/Pool | Future Cost | \$4,434.22 |
| Placed in Service | January 2024 | | |
| Useful Life | 7 | | |
| Replacement Year | 2031 | | |
| Remaining Life | 5 | | |



Good condition. Budget to recoat patio deck.

| io Deck - Resurface | e | 1 LS | @ \$11,000.00 |
|---------------------|-----------------|---------------------|---------------|
| Asset ID | 1030 | Asset Actual Cost | \$11,000.00 |
| | Recreation/Pool | Percent Replacement | 100% |
| Category | Recreation/Pool | Future Cost | \$19,288.57 |
| Placed in Service | September 2024 | | |
| Useful Life | 21 | | |
| Replacement Year | 2045 | | |
| Remaining Life | 19 | | |
| | | | |



Good condition. Budget to resurface patio deck. Approximately 1,530 SF.

Patio Deck - Resurface continued...

2024 - Curb Appeal resurfaced patio deck total \$10,145.

| Pool - Resurface | | 1 LS | @ \$25,682.90 |
|-------------------|-----------------|---------------------|---------------|
| Asset ID | 1039 | Asset Actual Cost | \$25,682.90 |
| | Recreation/Pool | Percent Replacement | 100% |
| Category | Recreation/Pool | Future Cost | \$28,906.33 |
| Placed in Service | January 2005 | | |
| Useful Life | 25 | | |
| Replacement Year | 2030 | | |
| Remaining Life | 4 | | |



Good condition. Budget to resurface and retile Pebble Tec pool.

2004 - Resurfaced total \$14,220.

| Pool Deck - Recoat | | 3,500 SF | @ \$3.50 |
|--------------------|-----------------|---------------------|-------------|
| Asset ID | 1044 | Asset Actual Cost | \$12,250.00 |
| | Recreation/Pool | Percent Replacement | 100% |
| Category | Recreation/Pool | Future Cost | \$17,989.54 |
| Placed in Service | January 2025 | | |
| Useful Life | 7 | | |
| Replacement Year | 2039 | | |
| Remaining Life | 13 | | |

Pool Deck - Recoat continued...



Poor condition. Budget to recoat pool deck. Noted faded and stained.

| Pool Deck - Resurface | | 3,500 SF | @ \$6.00 |
|-----------------------|-----------------|---------------------|-------------|
| Asset ID | 1045 | Asset Actual Cost | \$21,000.00 |
| | Recreation/Pool | Percent Replacement | 100% |
| Category | Recreation/Pool | Future Cost | \$25,075.10 |
| Placed in Service | January 2011 | | |
| Useful Life | 21 | | |
| Replacement Year | 2032 | | |
| Remaining Life | 6 | | |



Poor condition. Budget to recoat pool deck. Noted faded and stained.

| Spa - Resurface | | 1 LS | @ \$9,000.00 |
|-------------------|-----------------|---------------------|--------------|
| Asset ID | 1043 | Asset Actual Cost | \$9,000.00 |
| | Recreation/Pool | Percent Replacement | 100% |
| Category | Recreation/Pool | Future Cost | \$10,129.58 |
| Placed in Service | January 2005 | | |
| Useful Life | 25 | | |
| Replacement Year | 2030 | | |
| Remaining Life | 4 | | |





Good condition. Budget to resurface and retile both Pebble Tec spas.

Carport Roofs - Replace

No Useful Life

Asset ID 1017 Asset Actual Cost
Grounds Percent Replacement 100%
Category Roofing Future Cost
Placed in Service January 1991





Unfunded. Long life on metal corrugated carport roofs. Repairs normally operationally funded.

Roofs - Repair/Replace

Replacement Year Remaining Life

45,000 SF @ \$4.50 1016 \$202,500.00 Asset ID Asset Actual Cost Buildings Percent Replacement 100% Category Roofing **Future Cost** \$324,953.05 Placed in Service January 2012 Useful Life 30

2042

16





Duro-Last roof installed in 2012. Repairs performed as needed.

Duro-Last roofing is a brand of single-ply roofing membrane renowned for its exceptional

Roofs - Repair/Replace continued...

durability and ease of installation. Duro-Last is prefabricated in controlled factory conditions to ensure quality and consistency. Made of a flexible PVC (polyvinyl chloride) compound, Duro-Last membranes are engineered to withstand harsh weather conditions, UV exposure, and chemical exposure. Must have regular roof inspections, especially for seam integrity.

| Asphalt - Crack Seal | & Seal Coat | 1 LS | @ \$30,488.00 |
|----------------------|-----------------|---------------------|---------------|
| Asset ID | 1015 | Asset Actual Cost | \$30,488.00 |
| | Parking/Streets | Percent Replacement | 100% |
| Category | Streets/Asphalt | Future Cost | \$33,315.06 |
| Placed in Service | January 2024 | | |
| Useful Life | 5 | | |
| Replacement Year | 2029 | | |
| Remaining Life | 3 | | |



Budget to crack seal and seal coat. Approximately 161,000 SF. Placed in service end of 2023, used 2024 as date in service.

2023 - T & C Seal Coating sealcoated parking lot except boat and trailer storage areas total \$29,595.

| Asphalt - Remove & Replace | | 161,100 SF @ \$3.75 | | |
|----------------------------|-----------------|---------------------|--------------|--|
| Asset ID | 1013 | Asset Actual Cost | \$604,125.00 | |
| | Parking/Streets | Percent Replacement | 100% | |
| Category | Streets/Asphalt | Future Cost | \$811,893.48 | |
| Placed in Service | January 1991 | | | |
| Useful Life | 40 | | | |
| Adjustment | 5 | | | |
| Replacement Year | 2036 | | | |
| Remaining Life | 10 | | | |

Asphalt - Remove & Replace continued...



Budget to remove & replace asphalt. Extensive alligator cracking, however only a minor amount of break-up. If more areas begin to break-up, it is anticipated that the pavement will need to be removed and replaced. Future updates to this study should continue to evaluate the pavement and make appropriate adjustments in the useful life.

| Asphalt - S | lurry Seal |
|-------------|------------|
|-------------|------------|

Remaining Life

| spilati - Starry Scar | | 1 LS | (a) \$95,000.00 |
|-----------------------|-----------------|---------------------|-----------------|
| Asset ID | 1014 | Asset Actual Cost | \$95,000.00 |
| | Parking/Streets | Percent Replacement | 100% |
| Category | Streets/Asphalt | Future Cost | \$100,785.50 |
| Placed in Service | January 2020 | | |
| Useful Life | 8 | | |
| Replacement Year | 2028 | | |





Fair condition. Budget to slurry seal. Slurry seal is a wearing surface and not a structural fix but will temporarily cover the cracks. It should be covered with a seal coat within 1 or 2 years after application to protect it from UV damage. Approximately 161,100 SF.

2020 - T & C Coating slurry sealed parking lot total \$81,890.

| Flooring Carpet Out | door - Replace | 1 LS | @ \$87,000.00 |
|---------------------|----------------|---------------------|---------------|
| Asset ID | 1049 | Asset Actual Cost | \$87,000.00 |
| | Buildings | Percent Replacement | 100% |
| Category | Tree Trimming | Future Cost | \$89,610.00 |
| Placed in Service | January 2014 | | |
| Useful Life | 12 | | |
| Adjustment | 1 | | |
| Replacement Year | 2027 | | |
| Remaining Life | 1 | | |



Fair condition. Budget to replace commercial grade carpet located outdoors. Noted sun faded.

QUEENS BAY HOMEOWNERS ASSOCIATION Detail Index

| Asset ID Description | | Replacement | Page |
|----------------------------|--|-------------|--------------|
| Building Components | | | |
| 1065 | Black Pipe - Repair/Replace | 2026 | 1-9 |
| 1052 | Restrooms - Remodel | 2040 | 1-9 |
| Doors | & Windows | | |
| 1007 | ADA Door Openers - Replace | 2035 | 1-10 |
| 1009 | Doors & Windows - Replace | 2051 | 1-10 |
| | | | |
| Elevat | | 2020 | 1 10 |
| 1054 | Elevator (1) - Modernization | 2028 | 1-12 |
| 1066 | Elevator (2) - Modernization | 2030 | 1-12 |
| 1067 | Elevator (3) - Modernization | 2032 | 1-13 |
| 1068 | Elevator (4) - Modernization | 2034 | 1-14 |
| 1055 | Elevator - Cab Refurbish | 2040 | 1-15 |
| Equip | ment-Electrical | | |
| 1059 | Electric Panels - Replace | 2041 | 1-16 |
| Equip | ment-Grounds | | |
| 1056 | Gate Operator - Replace | 2028 | 1-17 |
| 1061 | Irrigation Controllers - Replace | 2028 | 1-17 |
| 1058 | Keypad - Replace | 2028 | 1-18 |
| 1003 | Pressure Regulator - Replace | 2030 | 1-18 |
| 1046 | Vacuum - Replace | 2028 | 1-19 |
| 1053 | Vehicles & Mower - Replace | 2029 | 1-20 |
| Fauin | mont Dool & Sno | | |
| 1031 | ment-Pool & Spa Pool Filters (A) - Replace | 2026 | 1-21 |
| 1031 | Pool Filters (B) - Replace | 2020 | 1-21 |
| 1036 | · · · · · · | 2032 | |
| 1033 | Pool Heater - Replace Pool/Spa Pumps & Motors - Repair/Replace | 2032 | 1-22 1-22 |
| 1038 | · · · · · · · · · · · · · · · · · · · | 2029 | 1-22 |
| | Spa Filters - Replace | 2029 | 1-23 |
| 1040 | Spa Heater (A) - Replace | 2020 | 1-24 |
| 1042 | Spa Heater (B) - Replace | 2032 | 1-24 |
| Fencin | g/Security | | |
| 1024 | Metal Fence - Repairs | 2026 | 1-25 |
| 1001 | Security System - Refurbish/Replace | 2030 | 1-25 |

QUEENS BAY HOMEOWNERS ASSOCIATION Detail Index

| Asset ID Description | | Replacement | Page |
|--|--|------------------------------|------------------------------|
| Fire Pr 1002 1064 1004 1005 | Backflow Preventers - Replace Check Valves & Fire Connections - Replace Fire Protection Components - Replace Sprinkler Heads - Test | 2044 2045 2048 2035 | 1-27 1-27 1-28 1-29 |
| Floorin 1048 1047 Furnish 1051 | Flooring Carpet Hallways - Replace Flooring Carpet Lobby - Replace hings-Interior Lobby Furnishings - Replace | 2037 2037 | 1-30 1-30 |
| 1006 | Roll Down Shades - Replace | 2051 | 1-32 |
| 1028 1033 1037 1062 | hings-Pool & Patio Patio Furnishings - Replace Patio Grills - Replace Pool Furnishings - Replace Pool Furnishings - Restrap ds Components | 2028 2032 2029 2034 | 1-34 1-34 1-35 1-36 |
| 1027 1057 | Fountain - Refurbish/Replacement Parts Guard Shack - Refurbish | 2032 2026 | 1-37 1-37 |
| HVAC 1012 1010 1011 | HVAC Elevators - Replace HVAC Hallways - Replace HVAC Lobby - Replace | 2028 2028 2027 | 1-38 1-38 1-39 |
| Lightin 1025 1026 | Bollard Lights - Replace Light Fixtures - Replace | 2032 2052 | 1-40 1-40 |
| Paintin 1018 1063 1019 1021 | Carport Structure - Paint Interior Lobby Ceiling - Paint Metal Components- Paint Stucco Trim - Paint | 2027 2035 2026 2031 | 1-42 1-42 1-43 1-43 |

QUEENS BAY HOMEOWNERS ASSOCIATION Detail Index

| Asset ID Description | | Replacement | Page |
|----------------------|-----------------------------------|-------------|------|
| Painting Continued | | | |
| 1020 | Stucco Walls - Paint | 2026 | 1-44 |
| Recrea | tion/Pool | | |
| 1029 | Patio Deck - Recoat | 2031 | 1-45 |
| 1030 | Patio Deck - Resurface | 2045 | 1-45 |
| 1039 | Pool - Resurface | 2030 | 1-46 |
| 1044 | Pool Deck - Recoat | 2039 | 1-46 |
| 1045 | Pool Deck - Resurface | 2032 | 1-47 |
| 1043 | Spa - Resurface | 2030 | 1-48 |
| Roofin | g | | |
| 1017 | Carport Roofs - Replace | 2026 | 1-49 |
| 1016 | Roofs - Repair/Replace | 2042 | 1-49 |
| Streets | /Asphalt | | |
| 1015 | Asphalt - Crack Seal & Seal Coat | 2029 | 1-51 |
| 1013 | Asphalt - Remove & Replace | 2036 | 1-51 |
| 1014 | Asphalt - Slurry Seal | 2028 | 1-52 |
| Tree Trimming | | | |
| 1049 | Flooring Carpet Outdoor - Replace | 2027 | 1-53 |
| | Total Funded Assets | 57 | |
| | Total Unfunded Assets | _4 | |
| | Total Assets | 61 | |

| Description | | Expenditures |
|---------------|--|-----------------|
| Replacemen | t Year 2026 | |
| Equipment- | Pool & Spa | |
| 1031 | Pool Filters (A) - Replace | 2,600 |
| 1038 | Pool/Spa Pumps & Motors - Repair/Replace | 2,600 |
| 1040 | Spa Heater (A) - Replace | 4,220 |
| Fencing/Sec | urity | |
| 1024 | Metal Fence - Repairs | 5,500 |
| Painting | - | |
| 1019 | Metal Components- Paint | 65,000 |
| 1020 | Stucco Walls - Paint | 11,970 |
| Total for 202 | 06 | \$91,890 |
| 10tai 101 202 | 20 | \$71,070 |
| Replacemen | t Year 2027 | |
| HVAC | | |
| 1011 | HVAC Lobby - Replace | 17,098 |
| Painting | • | |
| 1018 | Carport Structure - Paint | 25,750 |
| Tree Trimming | | |
| 1049 | Flooring Carpet Outdoor - Replace | 89,610 |
| Total for 202 | 27 | \$132,458 |
| Replacemen | t Vear 2028 | |
| Elevators | 11011 2020 | |
| 1054 | Elevator (1) - Modernization | 117,336 |
| | • • | 117,550 |
| Equipment- | Grounds Gate Operator - Replace | 4,244 |
| 1050 | Irrigation Controllers - Replace | 390 |
| 1051 | Keypad - Replace | 1,591 |
| 1036 | Vacuum - Replace | 2,016 |
| | - | 2,010 |
| | -Pool & Patio | 12 721 |
| 1028 | Patio Furnishings - Replace | 12,731 |
| HVAC | INVACED | 0.405 |
| 1012 | HVAC Elevators - Replace | 8,487 |
| 1010 | HVAC Hallways - Replace | 11,670 |
| Streets/Asph | | 400 = 0 = |
| 1014 | Asphalt - Slurry Seal | 100,785 |
| Total for 202 | 28 | \$259,249 |

| Description | Expenditures |
|---|----------------------|
| Replacement Year 2029 | |
| Equipment-Grounds | |
| 1053 Vehicles & Mower - Replace | 8,195 |
| Equipment-Pool & Spa | |
| 1041 Spa Filters - Replace | 3,642 |
| Furnishings-Pool & Patio | |
| 1037 Pool Furnishings - Replace | 21,855 |
| Streets/Asphalt | , |
| 1015 Asphalt - Crack Seal & Seal Coat | 33,315 |
| Total for 2029 | \$67,007 |
| 10tai 101 2029 | \$07,007 |
| Replacement Year 2030 | |
| Elevators | |
| 1066 Elevator (2) - Modernization | 124,481 |
| Equipment-Grounds | , |
| 1003 Pressure Regulator - Replace | 6,641 |
| Equipment-Pool & Spa | , |
| 1038 Pool/Spa Pumps & Motors - Repair/Replace | 2,926 |
| Fencing/Security | , |
| 1001 Security System - Refurbish/Replace | 12,943 |
| Furnishings-Interior | <i>y-</i> - |
| 1051 Lobby Furnishings - Replace | 41,876 |
| Recreation/Pool | 11,070 |
| 1039 Pool - Resurface | 28,906 |
| 1043 Spa - Resurface | 10,130 |
| Total for 2030 | \$227,903 |
| 10tai 101 2030 | \$221,703 |
| Replacement Year 2031 | |
| Fencing/Security | |
| 1024 Metal Fence - Repairs | 6,376 |
| Painting | • |
| 1021 Stucco Trim - Paint | 37,746 |
| Recreation/Pool | , |
| 1029 Patio Deck - Recoat | 4,434 |
| Total for 2031 | \$48,556 |

| Description | Expenditures |
|---|------------------|
| Replacement Year 2032 | |
| Elevators | |
| Elevator (3) - Modernization | 132,062 |
| Equipment-Pool & Spa | |
| 1035 Pool Heater - Replace | 14,329 |
| 1042 Spa Heater (B) - Replace | 5,039 |
| Furnishings-Pool & Patio | |
| Patio Grills - Replace | 2,627 |
| Grounds Components | |
| Fountain - Refurbish/Replacement Parts | 11,941 |
| Lighting | |
| 1025 Bollard Lights - Replace | 10,746 |
| Recreation/Pool | |
| Pool Deck - Resurface | 25,075 |
| Total for 2032 | \$201,819 |
| | 4-0-)0- 2 |
| Replacement Year 2033 | |
| Equipment-Grounds | |
| 1061 Irrigation Controllers - Replace | 452 |
| Total for 2033 | \$452 |
| 1000 101 2000 | Ψ 102 |
| Replacement Year 2034 | |
| Elevators | |
| 1068 Elevator (4) - Modernization | 140,105 |
| Equipment-Grounds | |
| 1053 Vehicles & Mower - Replace | 9,501 |
| Equipment-Pool & Spa | |
| 1038 Pool/Spa Pumps & Motors - Repair/Replace | 3,294 |
| 1040 Spa Heater (A) - Replace | 5,346 |
| Furnishings-Pool & Patio | |
| 1062 Pool Furnishings - Restrap | 8,487 |
| Streets/Asphalt | |
| 1015 Asphalt - Crack Seal & Seal Coat | 38,621 |
| Total for 2034 | \$205,354 |

| Description | | Expenditures |
|-------------------|--|-----------------|
| Replacemen | t Year 2035 | |
| Doors & Wi | ndows | |
| 1007 | ADA Door Openers - Replace | 13,048 |
| Equipment- | Pool & Spa | |
| 1041 | Spa Filters - Replace | 4,349 |
| Painting | | |
| 1063 | Interior Lobby Ceiling - Paint | 6,785 |
| Total for 20 | 35 | \$24,182 |
| Replacemen | t Year 2036 | |
| Equipment- | Grounds | |
| 1003 | Pressure Regulator - Replace | 7,929 |
| Fencing/Sec | urity | |
| 1024 | Metal Fence - Repairs | 7,392 |
| 1001 | Security System - Refurbish/Replace | 15,455 |
| Painting | | |
| 1019 | Metal Components- Paint | 87,355 |
| 1020 | Stucco Walls - Paint | 16,087 |
| Streets/Aspl | halt | |
| 1013 | Asphalt - Remove & Replace | 811,893 |
| 1014 | Asphalt - Slurry Seal | 127,672 |
| Total for 20 | 36 | \$1,073,782 |
| Renlacemen | at Year 2037 | |
| - | te Teal 2007 | |
| Flooring 1048 | Flooring Carpet Hallways - Replace | 47,341 |
| 1048 | Flooring Carpet Lobby - Replace | 6,910 |
| | Trooting Carpet Lobby Replace | 0,710 |
| Painting 1018 | Carport Structure - Paint | 34,606 |
| | • | |
| Total for 20 | 3/ | \$88,857 |
| Replacemen | t Year 2038 | |
| Equipment- | | |
| 1061 | Irrigation Controllers - Replace | 524 |
| Equipment- | Pool & Spa | |
| 1038 | Pool/Spa Pumps & Motors - Repair/Replace | 3,707 |

| Description | | Expenditures |
|--------------------|--|--------------|
| Replacement | t Year 2038 continued | |
| Furnishings | -Pool & Patio | |
| 1028 | Patio Furnishings - Replace | 17,109 |
| Recreation/l | Pool | |
| 1029 | Patio Deck - Recoat | 5,454 |
| Total for 203 | 38 | \$26,794 |
| Replacemen | t Year 2039 | |
| Equipment- | Grounds | |
| 1053 | Vehicles & Mower - Replace | 11,014 |
| Furnishings | -Pool & Patio | |
| 1037 | Pool Furnishings - Replace | 29,371 |
| Grounds Co | mponents | |
| 1027 | Fountain - Refurbish/Replacement Parts | 14,685 |
| Recreation/l | Pool | |
| 1044 | Pool Deck - Recoat | 17,990 |
| Streets/Aspl | nalt | |
| 1015 | Asphalt - Crack Seal & Seal Coat | 44,773 |
| Tree Trimm | S | |
| 1049 | Flooring Carpet Outdoor - Replace | 127,762 |
| Total for 203 | 39 | \$245,595 |
| Replacemen | t Year 2040 | |
| Building Co | mponents | |
| 1052 | Restrooms - Remodel | 30,252 |
| Elevators | | |
| 1055 | Elevator - Cab Refurbish | 148,234 |
| Equipment- | | |
| 1046 | Vacuum - Replace | 2,874 |
| Equipment- | Pool & Spa | |
| 1035 | Pool Heater - Replace | 18,151 |
| 1042 | Spa Heater (B) - Replace | 6,383 |
| _ | -Pool & Patio | |
| 1033 | Patio Grills - Replace | 3,328 |
| Total for 204 | 40 | \$209,221 |

| Description | | Expenditures |
|------------------------|--|------------------|
| Replacemen | t Year 2041 | |
| Equipment- | Electrical | |
| 1059 | Electric Panels - Replace | 24,927 |
| Equipment- | Pool & Spa | |
| 1036 | Pool Filters (B) - Replace | 3,967 |
| 1041 | Spa Filters - Replace | 5,193 |
| Fencing/Sec | urity | |
| 1024 | Metal Fence - Repairs | 8,569 |
| Painting | 1 | , |
| 1021 | Stucco Trim - Paint | 50,727 |
| Total for 204 | | \$93,38 4 |
| 10tai 101 20- | *1 | \$75,504 |
| Replacemen | t Year 2042 | |
| Equipment- | Grounds | |
| 1003 | Pressure Regulator - Replace | 9,468 |
| Equipment- | Pool & Spa | |
| 1038 | Pool/Spa Pumps & Motors - Repair/Replace | 4,172 |
| 1040 | Spa Heater (A) - Replace | 6,772 |
| Fencing/Sec | urity | |
| 1001 | Security System - Refurbish/Replace | 18,454 |
| Roofing | 1 | , |
| 1016 | Roofs - Repair/Replace | 324,953 |
| Total for 204 | | \$363,819 |
| Replacemen | t Vaar 2013 | |
| - | | |
| Equipment -1061 | | 607 |
| | Irrigation Controllers - Replace | |
| Total for 204 | 13 | \$607 |
| Replacemen | t Year 2044 | |
| Equipment- | Grounds | |
| 1053 | Vehicles & Mower - Replace | 12,768 |
| Equipment- | Pool & Spa | |
| 1031 | Pool Filters (A) - Replace | 4,426 |
| | | |

| Description | | Expenditures |
|-------------------|---|--------------|
| Replacement | Year 2044 continued | |
| Fire Protecti | on System | |
| 1002 | Backflow Preventers - Replace | 11,619 |
| Furnishings- | -Pool & Patio | |
| 1062 | Pool Furnishings - Restrap | 11,406 |
| Streets/Asph | alt | |
| 1015 | Asphalt - Crack Seal & Seal Coat | 51,904 |
| 1014 | Asphalt - Slurry Seal | 161,731 |
| Total for 204 | 14 | \$253,855 |
| Replacemen | t Year 2045 | |
| Fire Protecti | | |
| 1064 | Check Valves & Fire Connections - Replace | 1,710 |
| HVAC | 1 | , |
| 1011 | HVAC Lobby - Replace | 29,108 |
| Painting | | , |
| 1063 | Interior Lobby Ceiling - Paint | 9,118 |
| Recreation/I | , | , |
| 1030 | Patio Deck - Resurface | 19,289 |
| Total for 204 | 15 | \$59,225 |
| | | |
| Replacemen | t Year 2046 | |
| Equipment- | Grounds | |
| 1056 | Gate Operator - Replace | 7,224 |
| 1058 | Keypad - Replace | 2,709 |
| Equipment- | Pool & Spa | |
| 1038 | Pool/Spa Pumps & Motors - Repair/Replace | 4,696 |
| Fencing/Sec | urity | |
| 1024 | Metal Fence - Repairs | 9,934 |
| Grounds Co | mponents | |
| 1027 | Fountain - Refurbish/Replacement Parts | 18,061 |
| HVAC | | |
| 1012 | HVAC Elevators - Replace | 14,449 |
| 1010 | HVAC Hallways - Replace | 19,867 |
| Painting | | |
| 1019 | Metal Components- Paint | 117,397 |

| Description | | Expenditures |
|---------------------|--|----------------|
| Replacement 1020 | t Year 2046 continued Stucco Walls - Paint | 21,619 |
| Recreation/l | Pool | |
| 1044 | Pool Deck - Recoat | 22,125 |
| Total for 204 | 46 | \$238,082 |
| Replacemen | t Year 2047 | |
| Equipment- | Pool & Spa | |
| 1041 | Spa Filters - Replace | 6,201 |
| Painting | | |
| 1018 | Carport Structure - Paint | 46,507 |
| Total for 204 | 47 | \$52,708 |
| Replacemen | t Year 2048 | |
| Equipment- | Grounds | |
| 1061 | Irrigation Controllers - Replace | 704 |
| 1003 | Pressure Regulator - Replace | 11,305 |
| Equipment- | | |
| 1035 | Pool Heater - Replace | 22,993 |
| 1042 | Spa Heater (B) - Replace | 8,086 |
| Fencing/Sec | • | 22.025 |
| 1001 | Security System - Refurbish/Replace | 22,035 |
| Fire Protect | Fire Protection Components - Replace | 82,392 |
| | 1 1 | 02,392 |
| Furnishings 1051 | Lobby Furnishings - Replace | 71,290 |
| | -Pool & Patio | 71,270 |
| 1028 | Patio Furnishings - Replace | 22,993 |
| 1033 | Patio Grills - Replace | 4,215 |
| Total for 204 | - | \$246,015 |
| 10tai 101 20- | 10 | \$270,013 |
| - | t Year 2049 | |
| Equipment- | | |
| 1053 | Vehicles & Mower - Replace | 14,802 |
| Flooring | | ~ = .~= |
| 1048 | Flooring Carpet Hallways - Replace | 67,497 |

| Description | | Expenditures |
|--------------------|--|-----------------|
| Replacemen | t Year 2049 continued | |
| 1047 | Flooring Carpet Lobby - Replace | 9,852 |
| _ | -Pool & Patio | |
| 1037 | Pool Furnishings - Replace | 39,472 |
| Streets/Asph | | (0.171 |
| 1015 | Asphalt - Crack Seal & Seal Coat | 60,171 |
| Total for 204 | 49 | \$191,793 |
| Replacemen | t Year 2050 | |
| Equipment- | Pool & Spa | |
| 1038 | Pool/Spa Pumps & Motors - Repair/Replace | 5,285 |
| 1040 | Spa Heater (A) - Replace | 8,578 |
| Total for 205 | 50 | \$13,864 |
| Replacemen | t Year 2051 | |
| Doors & Wi | ndows | |
| 1009 | Doors & Windows - Replace | 502,507 |
| Fencing/Sec | · · | |
| 1024 | Metal Fence - Repairs | 11,516 |
| Furnishings | | |
| 1006 | Roll Down Shades - Replace | 41,876 |
| Painting | | 60.4 = 0 |
| 1021 | Stucco Trim - Paint | 68,173 |
| Tree Trimm 1049 | ing Flooring Carpet Outdoor - Replace | 182,159 |
| Total for 205 | | \$806,230 |
| Renlacemen | t Year 2052 | |
| Equipment- | | |
| 1046 | Vacuum - Replace | 4,098 |
| Lighting | | , |
| 1026 | Light Fixtures - Replace | 18,439 |
| Recreation/l | Pool | |
| 1029 | Patio Deck - Recoat | 8,249 |

| Description | | Expenditures |
|------------------------|--|-----------------|
| Replacemen | t Year 2052 continued | |
| Streets/Aspl | nalt | |
| 1014 | Asphalt - Slurry Seal | 204,876 |
| Total for 20: | 52 | \$235,662 |
| Replacemen | t Year 2053 | |
| Equipment- | Grounds | |
| 1061 | Irrigation Controllers - Replace | 816 |
| Equipment- | Pool & Spa | |
| 1041 | Spa Filters - Replace | 7,404 |
| Grounds Co | omponents | |
| 1027 | Fountain - Refurbish/Replacement Parts | 22,213 |
| Recreation/ | | |
| 1045 | Pool Deck - Resurface | 46,647 |
| Total for 2053 | | \$77,081 |
| Replacemen | t Year 2054 | |
| Equipment- | | |
| 1003 | Pressure Regulator - Replace | 13,499 |
| 1053 | Vehicles & Mower - Replace | 17,159 |
| Equipment- | - | , |
| 1038 | Pool/Spa Pumps & Motors - Repair/Replace | 5,949 |
| Fencing/Sec | | , |
| 1001 | Security System - Refurbish/Replace | 26,311 |
| Furnishings | -Pool & Patio | |
| 1062 | Pool Furnishings - Restrap | 15,329 |
| Streets/Aspl | - | |
| 1015 | Asphalt - Crack Seal & Seal Coat | 69,754 |
| Total for 2054 \$148,0 | | |
| Replacemen | t Year 2055 | |
| Doors & Wi | | |
| 1007 | ADA Door Openers - Replace | 23,566 |
| Painting | TELLE OUT OF CHOICE TESTINGO | 23,300 |
| 1063 | Interior Lobby Ceiling - Paint | 12,254 |

| Description | ı | Expenditures |
|-------------|------------------------|----------------------|
| Replaceme | nt Year 2055 continued | |
| Recreation | /Pool | |
| 1039 | Pool - Resurface | 60,523 |
| 1043 | Spa - Resurface | 21,209 |
| Total for 2 | 055 | \$117,552 |

QUEENS BAY HOMEOWNERS ASSOCIATION Spread Sheet

| 2026 2027 2028 2029 2030 2031 2032 2033 | 2034 | 2035 |
|---|---------|--------|
| ID Description | | |
| Building Components | | |
| 1065 Black Pipe - Repair/Replace Unfunded | | |
| 1052 Restrooms - Remodel | | |
| Building Components Total: | | |
| Doors & Windows | | |
| 1007 ADA Door Openers - Replace | | 13,048 |
| 1009 Doors & Windows - Replace | | |
| Doors & Windows Total: | | 13,048 |
| Elevators | | |
| 1054 Elevator (1) - Modernization 117,336 | | |
| 1066 Elevator (2) - Modernization 124,481 | | |
| 1067 Elevator (3) - Modernization | | |
| 1068 Elevator (4) - Modernization | 140,105 | |
| 1055 Elevator - Cab Refurbish | 11010 | |
| Elevators Total: 117,336 124,481 132,062 | 140,105 | |
| Equipment-Electrical | | |
| 1059 Electric Panels - Replace | | |
| Equipment-Electrical Total: | | |
| Equipment-Grounds | | |
| 1056 Gate Operator - Replace 4,244 | | |
| 1061 Irrigation Controllers - Replace 390 452 | | |
| 1058 Keypad - Replace 1,591 | | |
| 1003 Pressure Regulator - Replace 6,641 | | |
| 1046 Vacuum - Replace 2,016 | 0 | |
| 1053 Vehicles & Mower - Replace 8,195 | 9,501 | |
| Equipment-Grounds Total: 8,241 8,195 6,641 452 | 9,501 | |
| Equipment-Pool & Spa | | |
| 1031 Pool Filters (A) - Replace 2,600 | | |
| 1036 Pool Filters (B) - Replace | | |
| 1035 Pool Heater - Replace 14,329 | | |
| 1038 Pool/Spa Pumps & Motors - Repair/Replace 2,600 2,926 | 3,294 | |

QUEENS BAY HOMEOWNERS ASSOCIATION Spread Sheet

| | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 |
|---|------------|------|--------|--------|--------|-------|--------|------|-------|-------|
| ID Description | | | | | | | | | | |
| Equipment-Pool & Spa continued | | | | | | | | | | |
| 1041 Spa Filters - Replace | | | | 3,642 | | | | | | 4,349 |
| 1040 Spa Heater (A) - Replace | 4,220 | | | | | | | | 5,346 | |
| 1042 Spa Heater (B) - Replace | 0.420 | | | 2 (12 | 2.027 | | 5,039 | | 0.620 | 4 240 |
| Equipment-Pool & Spa Total: | 9,420 | | | 3,642 | 2,926 | | 19,368 | | 8,639 | 4,349 |
| Fencing/Security | | | | | | | | | | |
| 1024 Metal Fence - Repairs | 5,500 | | | | | 6,376 | | | | |
| 1001 Security System - Refurbish/Replace | | | | | 12,943 | | | | | |
| Fencing/Security Total: | 5,500 | | | | 12,943 | 6,376 | | | | |
| Fire Protection System | | | | | | | | | | |
| 1002 Backflow Preventers - Replace | | | | | | | | | | |
| 1064 Check Valves & Fire Connections - Replace | | | | | | | | | | |
| 1004 Fire Protection Components - Replace | T. C. 1. 1 | | | | | | | | | |
| 1005 Sprinkler Heads - Test Fire Protection System Total: | Unfunded | | | | | | | | | |
| • | | | | | | | | | | |
| Flooring | | | | | | | | | | |
| 1048 Flooring Carpet Hallways - Replace | | | | | | | | | | |
| 1047 Flooring Carpet Lobby - Replace | | | | | | | | | | |
| Flooring Total: | | | | | | | | | | |
| Furnishings-Interior | | | | | | | | | | |
| 1051 Lobby Furnishings - Replace | | | | | 41,876 | | | | | |
| 1006 Roll Down Shades - Replace | | | | | | | | | | |
| Furnishings-Interior Total: | | | | | 41,876 | | | | | |
| Furnishings-Pool & Patio | | | | | | | | | | |
| 1028 Patio Furnishings - Replace | | | 12,731 | | | | | | | |
| 1033 Patio Grills - Replace | | | | | | | 2,627 | | | |
| 1037 Pool Furnishings - Replace | | | | 21,855 | | | | | 0.405 | |
| 1062 Pool Furnishings - Restrap | | | 10 701 | 21.055 | | | 2 (27 | | 8,487 | |
| Furnishings-Pool & Patio Total: | | | 12,731 | 21,855 | | | 2,627 | | 8,487 | |

| | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 |
|---|----------|--------|--------|------|--------|--------|--------|------|------|-------|
| ID Description | | | | | | | | | | |
| Grounds Components | | | | | | | | | | |
| 1027 Fountain - Refurbish/Replacement Parts | | | | | | | 11,941 | | | |
| 1057 Guard Shack - Refurbish | Unfunded | | | | | | | | | |
| Grounds Components Total: | | | | | | | 11,941 | | | |
| HVAC | | | | | | | | | | |
| 1012 HVAC Elevators - Replace | | | 8,487 | | | | | | | |
| 1010 HVAC Hallways - Replace | | | 11,670 | | | | | | | |
| 1011 HVAC Lobby - Replace | | 17,098 | | | | | | | | |
| HVAC Total: | | 17,098 | 20,157 | | | | | | | |
| Lighting | | | | | | | | | | |
| 1025 Bollard Lights - Replace | | | | | | | 10,746 | | | |
| 1026 Light Fixtures - Replace | | | | | | | | | | |
| Lighting Total: | | | | | | | 10,746 | | | |
| Painting | | | | | | | | | | |
| 1018 Carport Structure - Paint | | 25,750 | | | | | | | | |
| 1063 Interior Lobby Ceiling - Paint | | | | | | | | | | 6,785 |
| 1019 Metal Components- Paint | 65,000 | | | | | | | | | |
| 1021 Stucco Trim - Paint | | | | | | 37,746 | | | | |
| 1020 Stucco Walls - Paint | 11,970 | | | | | | | | | |
| Painting Total: | 76,970 | 25,750 | | | | 37,746 | | | | 6,785 |
| Recreation/Pool | | | | | | | | | | |
| 1029 Patio Deck - Recoat | | | | | | 4,434 | | | | |
| 1030 Patio Deck - Resurface | | | | | | | | | | |
| 1039 Pool - Resurface | | | | | 28,906 | | | | | |
| 1044 Pool Deck - Recoat | | | | | | | 25.055 | | | |
| 1045 Pool Deck - Resurface | | | | | 10 120 | | 25,075 | | | |
| 1043 Spa - Resurface | | | | | 10,130 | 4 42 4 | 25.055 | | | |
| Recreation/Pool Total: | | | | | 39,036 | 4,434 | 25,075 | | | |
| Roofing | | | | | | | | | | |
| 1017 Carport Roofs - Replace | Unfunded | | | | | | | | | |
| 1016 Roofs - Repair/Replace | | | | | | | | | | |
| Roofing Total: | | | | | | | | | | |

| | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 |
|--|--------|---------|---------|--------|---------|--------|---------|------|---------|--------|
| ID Description | | | | | | | | | | |
| Streets/Asphalt | | | | | | | | | | |
| 1015 Asphalt - Crack Seal & Seal Coat | | | | 33,315 | | | | | 38,621 | |
| 1013 Asphalt - Remove & Replace | | | | | | | | | | |
| 1014 Asphalt - Slurry Seal | | | 100,785 | | | | | | | |
| Streets/Asphalt Total: | | | 100,785 | 33,315 | | | | | 38,621 | |
| Tree Trimming | | | | | | | | | | |
| 1049 Flooring Carpet Outdoor - Replace | | 89,610 | | | | | | | | |
| Tree Trimming Total: | | 89,610 | | | | | | | | |
| Year Total: | 91,890 | 132,458 | 259,249 | 67,007 | 227,903 | 48,556 | 201,819 | 452 | 205,354 | 24,182 |

| | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 | 2045 |
|---|--|------|-------|--------|---------|--------|-------|------|--------|------|
| ID Description | | | | | | | | | | |
| Building Components | | | | | | | | | | |
| 1065 Black Pipe - Repair/Replace | Unfunded | | | | | | | | | |
| 1052 Restrooms - Remodel | , and the second | | | | 30,252 | | | | | |
| Building Components Total: | | | | | 30,252 | | | | | |
| Doors & Windows | | | | | | | | | | |
| 1007 ADA Door Openers - Replace | | | | | | | | | | |
| 1009 Doors & Windows - Replace | | | | | | | | | | |
| Doors & Windows Total: | | | | | | | | | | |
| Elevators | | | | | | | | | | |
| 1054 Elevator (1) - Modernization | | | | | | | | | | |
| 1066 Elevator (2) - Modernization | | | | | | | | | | |
| 1067 Elevator (3) - Modernization | | | | | | | | | | |
| 1068 Elevator (4) - Modernization | | | | | | | | | | |
| 1055 Elevator - Cab Refurbish | | | | | 148,234 | | | | | |
| Elevators Total: | | | | | 148,234 | | | | | |
| Equipment-Electrical | | | | | | | | | | |
| 1059 Electric Panels - Replace | | | | | | 24,927 | | | | |
| Equipment-Electrical Total: | | | | | | 24,927 | | | | |
| Equipment-Grounds | | | | | | | | | | |
| 1056 Gate Operator - Replace | | | | | | | | | | |
| 1061 Irrigation Controllers - Replace | | | 524 | | | | | 607 | | |
| 1058 Keypad - Replace | | | | | | | | | | |
| 1003 Pressure Regulator - Replace | 7,929 | | | | | | 9,468 | | | |
| 1046 Vacuum - Replace | | | | | 2,874 | | | | | |
| 1053 Vehicles & Mower - Replace | | | | 11,014 | | | | | 12,768 | |
| Equipment-Grounds Total: | 7,929 | | 524 | 11,014 | 2,874 | | 9,468 | 607 | 12,768 | |
| Equipment-Pool & Spa | | | | | | | | | | |
| 1031 Pool Filters (A) - Replace | | | | | | | | | 4,426 | |
| 1036 Pool Filters (B) - Replace | | | | | | 3,967 | | | | |
| 1035 Pool Heater - Replace | | | | | 18,151 | | | | | |
| 1038 Pool/Spa Pumps & Motors - Repair/Replace | ; | | 3,707 | | | | 4,172 | | | |
| | | | | | | | | | | |

| | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 | 2045 |
|---|----------|-----------------|--------|--------|--------|-------|--------|------|--------|-------|
| ID Description | | | | | | | | | | |
| Equipment-Pool & Spa continued | | | | | | | | | | |
| 1041 Spa Filters - Replace | | | | | | 5,193 | | | | |
| 1040 Spa Heater (A) - Replace | | | | | 6.202 | | 6,772 | | | |
| 1042 Spa Heater (B) - Replace Equipment-Pool & Spa Total: | | | 3,707 | | 6,383 | 9,160 | 10,944 | | 4,426 | |
| | | | 3,707 | | 24,534 | 9,100 | 10,944 | | 4,420 | |
| Fencing/Security | | | | | | | | | | |
| 1024 Metal Fence - Repairs | 7,392 | | | | | 8,569 | 10.454 | | | |
| 1001 Security System - Refurbish/Replace | 15,455 | | | | | 9.5(0 | 18,454 | | | |
| Fencing/Security Total: | 22,847 | | | | | 8,569 | 18,454 | | | |
| Fire Protection System | | | | | | | | | | |
| 1002 Backflow Preventers - Replace | | | | | | | | | 11,619 | |
| 1064 Check Valves & Fire Connections - Replace | | | | | | | | | | 1,710 |
| 1004 Fire Protection Components - Replace1005 Sprinkler Heads - Test | Unfunded | | | | | | | | | |
| Fire Protection System Total: | Опјинава | | | | | | | | 11,619 | 1,710 |
| • | | | | | | | | | 11,012 | 1,.10 |
| Flooring | | 47.241 | | | | | | | | |
| 1048 Flooring Carpet Hallways - Replace 1047 Flooring Carpet Lobby - Replace | | 47,341 6,910 | | | | | | | | |
| Flooring Total: | | 54,251 | | | | | | | | |
| _ | | 34,231 | | | | | | | | |
| Furnishings-Interior | | | | | | | | | | |
| 1051 Lobby Furnishings - Replace | | | | | | | | | | |
| 1006 Roll Down Shades - Replace Furnishings-Interior Total: | | | | | | | | | | |
| | | | | | | | | | | |
| Furnishings-Pool & Patio | | | | | | | | | | |
| 1028 Patio Furnishings - Replace | | | 17,109 | | 2 220 | | | | | |
| 1033 Patio Grills - Replace1037 Pool Furnishings - Replace | | | | 29,371 | 3,328 | | | | | |
| 1062 Pool Furnishings - Replace | | | | 29,3/1 | | | | | 11,406 | |
| Furnishings-Pool & Patio Total: | | | 17,109 | 29,371 | 3,328 | | | | 11,406 | |

| | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 | 2045 |
|---|----------|--------|-------|--------|------|--------|---------|------|------|--------|
| ID Description | | | | | | | | | | |
| Grounds Components | | | | | | | | | | |
| 1027 Fountain - Refurbish/Replacement Parts | | | | 14,685 | | | | | | |
| 1057 Guard Shack - Refurbish | Unfunded | | | | | | | | | |
| Grounds Components Total: | | | | 14,685 | | | | | | |
| HVAC | | | | | | | | | | |
| 1012 HVAC Elevators - Replace | | | | | | | | | | |
| 1010 HVAC Hallways - Replace | | | | | | | | | | |
| 1011 HVAC Lobby - Replace | | | | | | | | | | 29,108 |
| HVAC Total: | | | | | | | | | | 29,108 |
| Tichtin c | | | | | | | | | | , . |
| Lighting | | | | | | | | | | |
| 1025 Bollard Lights - Replace | | | | | | | | | | |
| 1026 Light Fixtures - Replace | | | | | | | | | | |
| Lighting Total: | | | | | | | | | | |
| Painting | | | | | | | | | | |
| 1018 Carport Structure - Paint | | 34,606 | | | | | | | | |
| 1063 Interior Lobby Ceiling - Paint | | | | | | | | | | 9,118 |
| 1019 Metal Components- Paint | 87,355 | | | | | | | | | |
| 1021 Stucco Trim - Paint | | | | | | 50,727 | | | | |
| 1020 Stucco Walls - Paint | 16,087 | | | | | | | | | |
| Painting Total: | 103,441 | 34,606 | | | | 50,727 | | | | 9,118 |
| Recreation/Pool | | | | | | | | | | |
| 1029 Patio Deck - Recoat | | | 5,454 | | | | | | | |
| 1030 Patio Deck - Resurface | | | | | | | | | | 19,289 |
| 1039 Pool - Resurface | | | | | | | | | | |
| 1044 Pool Deck - Recoat | | | | 17,990 | | | | | | |
| 1045 Pool Deck - Resurface | | | | | | | | | | |
| 1043 Spa - Resurface | | | | | | | | | | |
| Recreation/Pool Total: | | | 5,454 | 17,990 | | | | | | 19,289 |
| Roofing | | | | | | | | | | |
| 1017 Carport Roofs - Replace | Unfunded | | | | | | | | | |
| 1016 Roofs - Repair/Replace | | | | | | | 324,953 | | | |
| Roofing Total: | | | | | | | 324,953 | | | |

| | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 | 2045 |
|--|-----------|--------|--------|---------|---------|--------|---------|------|---------|--------|
| ID Description | | | | | | | | | | |
| Streets/Asphalt | | | | | | | | | | |
| 1015 Asphalt - Crack Seal & Seal Coat | | | | 44,773 | | | | | 51,904 | |
| 1013 Asphalt - Remove & Replace | 811,893 | | | | | | | | | |
| 1014 Asphalt - Slurry Seal | 127,672 | | | | | | | | 161,731 | |
| Streets/Asphalt Total: | 939,566 | | | 44,773 | | | | | 213,635 | |
| Tree Trimming | | | | | | | | | | |
| 1049 Flooring Carpet Outdoor - Replace | | | | 127,762 | | | | | | |
| Tree Trimming Total: | | | | 127,762 | | | | | | |
| Year Total: | 1,073,782 | 88,857 | 26,794 | 245,595 | 209,221 | 93,384 | 363,819 | 607 | 253,855 | 59,225 |

| | 2046 | 2047 | 2048 | 2049 | 2050 | 2051 | 2052 | 2053 | 2054 | 2055 |
|---|--|------|--------|--------|-------|---------|-------|------|--------|--------|
| ID Description | | | | | | | | | | |
| Building Components | | | | | | | | | | |
| 1065 Black Pipe - Repair/Replace | Unfunded | | | | | | | | | |
| 1052 Restrooms - Remodel | , and the second | | | | | | | | | |
| Building Components Total: | | | | | | | | | | |
| Doors & Windows | | | | | | | | | | |
| 1007 ADA Door Openers - Replace | | | | | | | | | | 23,566 |
| 1009 Doors & Windows - Replace | | | | | | 502,507 | | | | |
| Doors & Windows Total: | | | | | | 502,507 | | | | 23,566 |
| Elevators | | | | | | | | | | |
| 1054 Elevator (1) - Modernization | | | | | | | | | | |
| 1066 Elevator (2) - Modernization | | | | | | | | | | |
| 1067 Elevator (3) - Modernization | | | | | | | | | | |
| 1068 Elevator (4) - Modernization | | | | | | | | | | |
| 1055 Elevator - Cab Refurbish | | | | | | | | | | |
| Elevators Total: | | | | | | | | | | |
| Equipment-Electrical | | | | | | | | | | |
| 1059 Electric Panels - Replace | | | | | | | | | | |
| Equipment-Electrical Total: | | | | | | | | | | |
| Equipment-Grounds | | | | | | | | | | |
| 1056 Gate Operator - Replace | 7,224 | | | | | | | | | |
| 1061 Irrigation Controllers - Replace | | | 704 | | | | | 816 | | |
| 1058 Keypad - Replace | 2,709 | | | | | | | | | |
| 1003 Pressure Regulator - Replace | | | 11,305 | | | | | | 13,499 | |
| 1046 Vacuum - Replace | | | | | | | 4,098 | | | |
| 1053 Vehicles & Mower - Replace | | | | 14,802 | | | | | 17,159 | |
| Equipment-Grounds Total: | 9,934 | | 12,009 | 14,802 | | | 4,098 | 816 | 30,658 | |
| Equipment-Pool & Spa | | | | | | | | | | |
| 1031 Pool Filters (A) - Replace | | | | | | | | | | |
| 1036 Pool Filters (B) - Replace | | | | | | | | | | |
| 1035 Pool Heater - Replace | | | 22,993 | | | | | | | |
| 1038 Pool/Spa Pumps & Motors - Repair/Replace | 4,696 | | | | 5,285 | | | | 5,949 | |
| | | | | | | | | | | |

| | 2046 | 2047 | 2048 | 2049 | 2050 | 2051 | 2052 | 2053 | 2054 | 2055 |
|---|-----------|-------|--------|--------|--------|--------|------|-------|-----------|------|
| ID Description | | | | | | | | | | |
| Equipment-Pool & Spa continued | | | | | | | | | | |
| 1041 Spa Filters - Replace | | 6,201 | | | | | | 7,404 | | |
| 1040 Spa Heater (A) - Replace | | | 0.004 | | 8,578 | | | | | |
| 1042 Spa Heater (B) - Replace | 4.606 | (201 | 8,086 | | 12.074 | | | 7.404 | 5.040 | |
| Equipment-Pool & Spa Total: | 4,696 | 6,201 | 31,079 | | 13,864 | | | 7,404 | 5,949 | |
| Fencing/Security | | | | | | | | | | |
| 1024 Metal Fence - Repairs | 9,934 | | | | | 11,516 | | | | |
| 1001 Security System - Refurbish/Replace | | | 22,035 | | | | | | 26,311 | |
| Fencing/Security Total: | 9,934 | | 22,035 | | | 11,516 | | | 26,311 | |
| Fire Protection System | | | | | | | | | | |
| 1002 Backflow Preventers - Replace | | | | | | | | | | |
| 1064 Check Valves & Fire Connections - Replace | | | | | | | | | | |
| 1004 Fire Protection Components - Replace | T. C. 1.1 | | 82,392 | | | | | | | |
| 1005 Sprinkler Heads - Test Fire Protection System Total: | Unfunded | | 82,392 | | | | | | | |
| • | | | 82,392 | | | | | | | |
| Flooring | | | | | | | | | | |
| 1048 Flooring Carpet Hallways - Replace | | | | 67,497 | | | | | | |
| 1047 Flooring Carpet Lobby - Replace | | | | 9,852 | | | | | | |
| Flooring Total: | | | | 77,349 | | | | | | |
| Furnishings-Interior | | | | | | | | | | |
| 1051 Lobby Furnishings - Replace | | | 71,290 | | | | | | | |
| 1006 Roll Down Shades - Replace | | | | | | 41,876 | | | | |
| Furnishings-Interior Total: | | | 71,290 | | | 41,876 | | | | |
| Furnishings-Pool & Patio | | | | | | | | | | |
| 1028 Patio Furnishings - Replace | | | 22,993 | | | | | | | |
| 1033 Patio Grills - Replace | | | 4,215 | | | | | | | |
| 1037 Pool Furnishings - Replace | | | | 39,472 | | | | | 4 = 6 = = | |
| 1062 Pool Furnishings - Restrap | | | 27.200 | 20.452 | | | | | 15,329 | |
| Furnishings-Pool & Patio Total: | | | 27,209 | 39,472 | | | | | 15,329 | |

| Description Grounds Components Grounds Components Total: Grounds Components Components Total: Grounds Components Total: Grounds Components Total: Grounds Components Comp | | 2046 | 2047 | 2048 | 2049 | 2050 | 2051 | 2052 | 2053 | 2054 | 2055 |
|--|--------------------------|----------|--------|------|------|------|--------|--------|--------|------|--------|
| 102 Fountain - Refurbish/Replacement Paris 18,061 | ID Description | | | | | | | | | | |
| 102 Fountain - Refurbish/Replacement Paris 18,061 | - | | | | | | | | | | |
| 1057 Giard Shack - Refurbish 18,061 22,213 HVAC | | 18 061 | | | | | | | 22 213 | | |
| Figure F | | | | | | | | | 22,213 | | |
| HVAC 1012 HVAC Elevators - Replace 14,449 19,867 | | | | | | | | | 22,213 | | |
| 1012 HVAC Elevators - Replace 14,449 19,867 19,86 | • | 10,001 | | | | | | | , | | |
| 101 HVAC Hallways - Replace 19,867 | | | | | | | | | | | |
| NAC Total: 34,316 | | | | | | | | | | | |
| HVAC Total: 34,316 | | 19,867 | | | | | | | | | |
| Lighting 1025 Bollard Lights - Replace 18,439 | | | | | | | | | | | |
| 10.25 Bollard Lights - Replace 18,439 | HVAC Total: | 34,316 | | | | | | | | | |
| 10.25 Bollard Lights - Replace 18,439 | Lighting | | | | | | | | | | |
| 1026 Light Fixtures - Replace 18,439 | | | | | | | | | | | |
| Painting Painting | | | | | | | | 18,439 | | | |
| 1018 Carport Structure - Paint 46,507 102,54 1019 Metal Components - Paint 117,397 117,397 117,397 117,397 117,397 1021 Stucco Trim - Paint 21,619 139,016 46,507 68,173 12,254 12,254 139,016 139,016 139,016 146,507 12,254 139,016 139, | | _ | | | | | | | | | |
| 1018 Carport Structure - Paint 46,507 102,54 1019 Metal Components - Paint 117,397 117,397 117,397 117,397 117,397 1021 Stucco Trim - Paint 21,619 139,016 46,507 68,173 12,254 12,254 139,016 139,016 139,016 146,507 12,254 139,016 139, | | | | | | | | | | | |
| 1063 Interior Lobby Ceiling - Paint 117,397 117,397 1021 Stucco Trim - Paint 68,173 1020 Stucco Walls - Paint 21,619 79 1020 Stucco Walls - Paint 139,016 46,507 68,173 12,254 12,254 139,016 139, | | | 16 507 | | | | | | | | |
| 1019 Metal Components- Paint 117,397 1021 Stucco Trim - Paint 21,619 | | | 40,307 | | | | | | | | 12.254 |
| 1021 Stucco Trim - Paint 21,619 | | 117 207 | | | | | | | | | 12,234 |
| 1020 Stucco Walls - Paint 21,619 | | 117,397 | | | | | 68 173 | | | | |
| Painting Total: 139,016 46,507 68,173 12,254 Recreation/Pool 1029 Patio Deck - Recoat 8,249 1030 Patio Deck - Resurface 60,523 1034 Pool Deck - Resurface 22,125 1045 Pool Deck - Resurface 46,647 1043 Spa - Resurface 21,209 Recreation/Pool Total: 22,125 Roofing 8,249 46,647 1017 Carport Roofs - Replace Unfunded 1016 Roofs - Repair/Replace Unfunded | | 21.610 | | | | | 06,173 | | | | |
| Recreation/Pool 1029 Patio Deck - Recoat 8,249 1030 Patio Deck - Resurface 60,523 1044 Pool Deck - Recoat 22,125 1045 Pool Deck - Resurface 46,647 1043 Spa - Resurface 21,209 Recreation/Pool Total: 22,125 Roofing 1017 Carport Roofs - Replace Unfunded 1016 Roofs - Repair/Replace Unfunded | | | 46 507 | | | | 68 173 | | | | 12 254 |
| 1029 Patio Deck - Recoat 8,249 1030 Patio Deck - Resurface 60,523 1039 Pool - Resurface 22,125 1045 Pool Deck - Resurface 46,647 1043 Spa - Resurface 21,209 Recreation/Pool Total: 22,125 8,249 46,647 Roofing 1017 Carport Roofs - Replace Unfunded 1016 Roofs - Repair/Replace Unfunded 1017 Roofs - Repair/Replace Unfunded 1018 Roofs - Repair/Replace Unfunded 1019 Roofs - Repair/Replace Roofs - Repair/Replace Unfunded 1019 Roofs - Repair/Replace Roofs - Repair/Replace Roofs - Ro | | 137,010 | 40,507 | | | | 00,175 | | | | 12,234 |
| 1030 Patio Deck - Resurface 60,523 1039 Pool - Resurface 60,523 1044 Pool Deck - Recoat 22,125 1045 Pool Deck - Resurface 46,647 1043 Spa - Resurface 21,209 Recreation/Pool Total: 22,125 Roofing 1017 Carport Roofs - Replace Unfunded 1016 Roofs - Repair/Replace | Recreation/Pool | | | | | | | | | | |
| 1039 Pool - Resurface 60,523 1044 Pool Deck - Recoat 22,125 1045 Pool Deck - Resurface 46,647 1043 Spa - Resurface 21,209 Recreation/Pool Total: 22,125 8,249 46,647 81,733 Roofing 1017 Carport Roofs - Replace Unfunded Unfunded 1016 Roofs - Repair/Replace Unfunded Unfunded | 1029 Patio Deck - Recoat | | | | | | | 8,249 | | | |
| 1044 Pool Deck - Recoat 22,125 1045 Pool Deck - Resurface 46,647 1043 Spa - Resurface 21,209 Recreation/Pool Total: 22,125 8,249 46,647 81,733 Roofing 1017 Carport Roofs - Replace Unfunded 1016 Roofs - Repair/Replace Unfunded | | | | | | | | | | | |
| 1045 Pool Deck - Resurface 46,647 1043 Spa - Resurface 21,209 Recreation/Pool Total: 22,125 8,249 46,647 81,733 Roofing 1017 Carport Roofs - Replace Unfunded 1016 Roofs - Repair/Replace Unfunded | | | | | | | | | | | 60,523 |
| 1043 Spa - Resurface | | 22,125 | | | | | | | | | |
| Recreation/Pool Total: 22,125 Roofing 1017 Carport Roofs - Replace 1016 Roofs - Repair/Replace Unfunded | | | | | | | | | 46,647 | | |
| Roofing 1017 Carport Roofs - Replace Unfunded 1016 Roofs - Repair/Replace | | | | | | | | | | | |
| 1017 Carport Roofs - Replace Unfunded 1016 Roofs - Repair/Replace | Recreation/Pool Total: | 22,125 | | | | | | 8,249 | 46,647 | | 81,733 |
| 1017 Carport Roofs - Replace Unfunded 1016 Roofs - Repair/Replace | Roofing | | | | | | | | | | |
| 1016 Roofs - Repair/Replace | | Unfunded | | | | | | | | | |
| | | v | | | | | | | | | |
| ullet | Roofing Total: | | | | | | | | | | |

| | 2046 | 2047 | 2048 | 2049 | 2050 | 2051 | 2052 | 2053 | 2054 | 2055 |
|--|---------|--------|---------|---------|--------|---------|---------|--------|---------|---------|
| ID Description | | | | | | | | | | |
| Streets/Asphalt | | | | | | | | | | |
| 1015 Asphalt - Crack Seal & Seal Coat | | | | 60,171 | | | | | 69,754 | |
| 1013 Asphalt - Remove & Replace | | | | | | | | | | |
| 1014 Asphalt - Slurry Seal | | | | | | | 204,876 | | | |
| Streets/Asphalt Total: | | | | 60,171 | | | 204,876 | | 69,754 | |
| Tree Trimming | | | | | | | | | | |
| 1049 Flooring Carpet Outdoor - Replace | | | | | | 182,159 | | | | |
| Tree Trimming Total: | | | | | | 182,159 | | | | |
| Year Total: | 238,082 | 52,708 | 246,015 | 191,793 | 13,864 | 806,230 | 235,662 | 77,081 | 148,001 | 117,552 |

Important Information

The client shall have the right to reproduce and distribute copies of this report, or the information contained within, as may be required for compliance with all applicable regulations.

This reserve analysis study and the parameters under which it has been completed are based upon information provided to us in part by representatives of the association, its contractors and vendors and our own experience with local costs. We also may rely on various construction pricing and scheduling manuals including, but not limited to: Marshall & Swift Valuation Service, RS Means Facilities Maintenance & Repair Cost Data, RS Means Repair & Remodeling Cost Data, National Construction Estimator, National Repair & Remodel Estimator, Dodge Cost Manual and McGraw-Hill Professional, if needed.

It has been assumed, unless otherwise noted in this report, that all assets have been designed and constructed properly and that each estimated useful life will approximate that of the norm per industry standards and/or manufacturer's specifications. In some cases, estimates may have been used on assets, which have an indeterminable but potential liability to the association. The decision for the inclusion of these as well as all assets considered is left to the client.

This reserve analysis study is a reflection of information provided to or assembled by the consultant for the association's use, not for the purpose of performing an audit, quality/forensic analyses or background checks of historical records. Information provided by the official representative of the association regarding financial, physical, quantity, or historical issues is deemed reliable by the consultant.

We recommend that your reserve analysis study be updated on an annual basis due to fluctuating interest rates, inflationary changes, and the unpredictable nature of the lives of many of the assets under consideration. All of the information collected during our inspection of the association and computations made subsequently in preparing this reserve analysis study are retained in our computer files. Therefore, annual updates may be completed quickly and inexpensively each year.

FDReserve Studies would like to thank you for using our services. We invite you to call us at any time, should you have questions, comments or need assistance. In addition, any of the parameters and estimates used in this study may be changed at your request, after which we will provide a revised study.

This reserve analysis is prepared under the supervision of William A. Schlimgen PE, a registered professional engineer in Arizona with more than 10 years of experience in preparation of reserve studies and more than 40 years of engineering management, design, inspection and construction management experience.

Part I

Document

This reserve analysis study is provided as an aid for planning purposes and not as an accounting tool. Since it deals with events yet to take place, there is no assurance that the results enumerated within it will, in fact, occur as described.

Preparing the annual budget and overseeing the association's finances are perhaps the most important responsibilities of board members. The annual operating and reserve budgets reflect the planning and goals of the association and set the level and quality of service for all of the association's activities.

Funding Options

When a major repair or replacement is required in a community, an association has essentially four options available to address the expenditure:

The first, and only logical means that the Board of Directors has to ensure its ability to maintain the assets for which it is obligated, is by assessing an adequate level of reserves as part of the regular membership assessment, thereby distributing the cost of the replacements uniformly over the entire membership. The community is not only comprised of present members, but also future members. Any decision by the Board of Directors to adopt a calculation method or funding plan which would disproportionately burden future members in order to make up for past reserve deficits, would be a breach of its fiduciary responsibility to those future members. Unlike individuals determining their own course of action, the board is responsible to the "community" as a whole.

Whereas, if the association was setting aside reserves for this purpose, using the vehicle of the regularly assessed membership dues, it would have had the full term of the life of the roof, for example, to accumulate the necessary moneys. Additionally, those contributions would have been evenly distributed over the entire membership and would have earned interest as part of that contribution.

The second option is for the association to **acquire a loan** from a lending institution in order to effect the required repairs. In many cases, banks will lend to an association using "future homeowner assessments" as collateral for the loan. With this method, the <u>current</u> board is pledging the <u>future</u> assets of an association. They are also incurring the additional expense of interest fees along with the original principal amount. In the case of a \$150,000 roofing replacement, the association may be required to pay back the loan over a three to five year period, with interest.

The third option, too often used, is simply to **defer the required repair or replacement**. This option, which is not recommended, can create an environment of declining property values due to expanding lists of deferred maintenance items and the association's financial inability to keep pace with the normal aging process of the common area components. This, in turn, can have a seriously negative impact on sellers in the association by making it difficult, or even impossible, for potential buyers to obtain financing from lenders. Increasingly, lending institutions are requesting copies of the association's most recent reserve study before granting loans, either for the association itself, a prospective purchaser, or for an individual within such an association.

The fourth option is to pass a "special assessment" to the membership in an amount required to cover the expenditure. When a special assessment is passed, the association has the authority and responsibility to collect the assessments, even by means of foreclosure, if necessary. However, an

association considering a special assessment cannot guarantee that an assessment, when needed, will be passed. Consequently, the association cannot guarantee its ability to perform the required repairs or replacements to those major components for which it is obligated when the need arises. Additionally, while relatively new communities require very little in the way of major "reserve" expenditures, associations reaching 12 to 15 years of age and older, find many components reaching the end of their effective useful lives. These required expenditures, all accruing at the same time, could be devastating to an association's overall budget.

Types of Reserve Studies

Most reserve studies fit into one of three categories:

Full Reserve Study;

Update with site inspection; and

Update without site inspection.

In a **Full Reserve Study**, the reserve provider conducts a component inventory, a condition assessment (based upon on-site visual observations), and life and valuation estimates to determine both a "fund status" and "funding plan".

In an **Update <u>with</u> site inspection**, the reserve provider conducts a component inventory (verification only, not quantification unless new components have been added to the inventory), a condition assessment (based upon on-site visual observations), and life and valuation estimates to determine both the "fund status and "funding plan."

In an **Update** <u>without</u> site inspection, the reserve provider conducts life and valuation estimates to determine the "fund status" and "funding plan."

The Reserve Study: A Physical and a Financial Analysis

There are two components of a reserve study: a physical analysis and a financial analysis.

Physical Analysis

During the physical analysis, a reserve study provider evaluates information regarding the physical status and repair/replacement cost of the association's major common area components. To do so, the provider conducts a component inventory, a condition assessment, and life and valuation estimates.

Developing a Component List

The budget process begins with full inventory of all the major components for which the association is responsible. The determination of whether an expense should be labeled as operational, reserve, or excluded altogether is sometimes subjective. Since this labeling may have a major impact on the financial plans of the association, subjective determinations should be minimized. We suggest the following considerations when labeling an expense.

Operational Expenses

Occur at least annually, no matter how large the expense, and can be budgeted for effectively each year. They are characterized as being reasonably predictable, both in terms of frequency and cost. Operational expenses include all minor expenses, which would not otherwise adversely affect an operational budget from one year to the next.

Reserve Expenses

These are major expenses that occur other than annually, and which must be budgeted for in advance in order to ensure the availability of the necessary funds in time for their use. Reserve expenses are reasonably predictable both in terms of frequency and cost. However, they may include significant assets that have an indeterminable but potential liability that may be demonstrated as a likely occurrence. They are expenses that, when incurred, would have a significant effect on the smooth operation of the budgetary process from one year to the next, if they were not reserved for in advance.

Budgeting is Normally Excluded

For expenses that are necessitated by acts of nature, accidents or other occurrences that are more properly insured for, rather than reserved for.

Financial Analysis

The financial analysis assesses the association's reserve balance or "fund status" (measured in cash or as percent fully funded) to determine a recommendation for the appropriate reserve contribution rate in the future, known as the "funding plan".

Preparing the Reserve Study

Once the reserve assets have been identified and quantified, their respective replacement costs, useful lives and remaining lives must be assigned so that a funding schedule can be constructed. Replacement costs and useful lives can be found in published manuals such as construction estimators, appraisal handbooks, and valuation guides. Remaining lives are calculated from the useful lives and ages of assets and adjusted according to conditions such as design, manufactured quality, usage, exposure to the elements and maintenance history.

By following the recommendations of an effective reserve study, the association should avoid any major shortfalls. However, to remain accurate, the report should be updated on an annual basis to reflect such changes as shifts in economic parameters, additions of phases or assets, or expenditures of reserve funds. The association can assist in simplifying the reserve analysis update process by keeping accurate records of these changes throughout the year.

Funding Methods

From the simplest to the most complex, reserve analysis providers use many different computational processes to calculate reserve requirements. However, there are two basic processes identified as industry standards: the cash flow method and the component method.

The cash flow method develops a reserve-funding plan where contributions to the reserve fund are designed to offset the variable annual expenditures from the reserve fund. Different reserve funding plans are tested against the actual anticipated schedule of reserve expenses until the desired funding goal is achieved. This method sets up a "window" in which all future anticipated replacement costs are computed, based upon the individual lives of the components under consideration. The Threshold and the Current Assessment funding models are based upon the cash flow method.

The component method develops a reserve-funding plan where the total contribution is based upon the sum of contributions for individual components. The component method is the more conservative of the two funding options, and assures that the association will achieve and maintain an ideal level of reserve over time. This method also allows for computations on individual components in the analysis. The Component Funding model is based upon the component methodology.

Funding Strategies

Once an association has established its funding goals, the association can select an appropriate funding plan. There are four basic strategies from which most associations select. It is recommended that associations consult professionals to determine the best strategy or combination of plans that best suit the association's need. Additionally, associations should consult with their financial advisor to determine the tax implications of selecting a particular plan. Further, consultation with the American Institute of Certified Public Accountants (AICPA) for their reporting requirements is advisable. The four funding plans and descriptions of each are detailed below. Associations will have to update their reserve studies more or less frequently depending on the funding strategy they select.

Full Funding---Given that the basis of funding for reserves is to distribute the costs of the replacements over the lives of the components in question, it follows that the ideal level of reserves would be proportionately related to those lives and costs. If an association has a component with an expected estimated useful life of ten years, it would set aside approximately one-tenth of the replacement cost each year. At the end of three years, one would expect three-tenths of the replacement cost to have accumulated, and if so, that component would be "fully-funded." This model is important in that it is a measure of the adequacy of an association's reserves at any one point of time, and is independent of any particular method which may have been used for past funding or may be under consideration for future funding. This formula represents a snapshot in time and is based upon current replacement cost, independent of future inflationary or investment factors:

Fully Funded Reserves = Age divided by Useful Life the results multiplied by Current Replacement Cost

When an association's total accumulated reserves for all components meet this criterion, its reserves are considered "fully-funded."

The **Threshold Funding Model (Minimum Funding)**. The goal of this funding method is to keep the reserve cash balance above zero. This means that while each individual component may not be fully funded, the reserve balance overall does not drop below zero during the projected period. An association using this funding method must understand that even a minor reduction in a component's remaining useful life can result in a deficit in the reserve cash balance.

The **Threshold Funding Model.** This method is based upon the cash flow funding concept. The minimum reserve cash balance in threshold funding, however, is set at a predetermined dollar amount (other than \$0).

The Current Assessment Funding Model. This method is also based upon the cash flow funding concept. The initial reserve assessment is set at the association's current fiscal year funding level and a 30-year projection is calculated to illustrate the adequacy of the current funding over time.

The Component Funding Model. This is a straight-line funding model. It distributes the cash reserves to individual reserve components and then calculates what the reserve assessment and interest contribution (minus taxes) should be, again by each reserve component. The current annual assessment is then determined by summing all the individual component assessments, hence the name "Component Funding Model". This is the most conservative funding model. It leads to or maintains the fully funded reserve position. The following details this calculation process.

Component Funding Model Distribution of Accumulated Reserves

The "Distribution of Accumulated Reserves Report" is a "Component Funding Model" calculation. This distribution **does not** apply to the cash flow funding models.

When calculating reserves based upon the component methodology, a beginning reserve balance must be allocated for each of the individual components considered in the analysis, before the individual calculations can be completed. When this distribution is not available, or of sufficient detail, the following method is suggested for allocating reserves:

The first step the program performs in this process is subtracting, from the total accumulated reserves, any amounts for assets that have predetermined (fixed) reserve balances. The user can "fix" the accumulated reserve balance within the program on the individual asset's detail page. If, by error, these amounts total more than the amount of funds available, then the remaining assets are adjusted accordingly. A provision for a contingency reserve is then deducted by the determined percentage used, and if there are sufficient remaining funds available.

The second step is to identify the ideal level of reserves for each asset. As indicated in the prior section, this is accomplished by evaluating the component's age proportionate to its estimated useful life and current replacement cost. Again, the equation used is as follows:

Fully Funded Reserves = (Age/Useful Life) x Current Replacement Cost

The software program performs the above calculations to the actual month the component was placed-in-service. The program projects that the accumulation of necessary reserves for repairs or replacements will be available on the first day of the fiscal year in which they are scheduled to occur.

The next step the program performs is to arrange all of the assets used in the study in ascending order by remaining life, and alphabetically within each grouping of remaining life items. These assets are then assigned their respective ideal level of reserves until the amount of funds available is depleted, or until all assets are appropriately funded. If any assets are assigned a zero remaining life (scheduled for replacement in the current fiscal year), then the amount assigned equals the current replacement cost and funding begins for the next cycle of replacement. If there are insufficient funds available to accomplish this, then the software automatically adjusts the zero remaining life items to one year, and that asset assumes its new grouping position alphabetically in the final printed report.

If, at the completion of this task, there are additional moneys that have not been distributed, the remaining reserves are then assigned, in ascending order, to a level equal to, but not exceeding, the current replacement cost for each component. If there are sufficient moneys available to fund all assets at their current replacement cost levels, then any excess funds are designated as such and are not factored into any of the report computations. If, at the end of this assignment process there are designated excess funds, they can be used to offset the monthly contribution requirements recommended, or used in any other manner the client may desire.

Assigning the reserves in this manner defers the make-up period for any under-funding over the longest remaining life of all assets under consideration, thereby minimizing the impact of any deficiency. For example, if the report indicates an under funding of \$50,000, this under-funding will be assigned to components with the longest remaining lives in order to give more time to "replenish" the account. If the \$50,000 under-funding were to be assigned to short remaining life items, the impact would be felt

immediately.

If the reserves are under-funded, the monthly contribution requirements, as outlined in this report, can be expected to be higher than normal. In future years, as individual assets are replaced, the funding requirements will return to their normal levels. In the case of a large deficiency, a special assessment may be considered. The program can easily generate revised reports outlining how the monthly contributions would be affected by such an adjustment, or by any other changes that may be under consideration.

Funding Reserves

Three assessment and contribution figures are provided in the report, the "Monthly Reserve Assessment Required", the "Average Net Monthly Interest Earned" contribution and the "Total Monthly Allocation to Reserves." The association should allocate the "Monthly Reserve Assessment Required" amount to reserves each month when the interest earned on the reserves is left in the reserve accounts as part of the contribution. Any interest earned on reserve deposits, must be left in reserves and only amounts set aside for taxes should be removed.

The second alternative is to allocate the "Total Monthly Allocation" to reserves (this is the member assessment plus the anticipated interest earned for the fiscal year). This method assumes that all interest earned will be assigned directly as operating income. This allocation takes into consideration the anticipated interest earned on accumulated reserves regardless of whether or not it is actually earned. When taxes are paid, the amount due will be taken directly from the association's operating accounts as the reserve accounts are allocated only those moneys net of taxes.

Users' Guide to your Reserve Analysis Study

Part II of your report contains the reserve analysis study for your association. There are seven types of reports in the study as described below.

Report Summaries

The Report Summary for all funding models lists all of the parameters that were used in calculating the report

The Component Listing/Summary lists all assets by category (i.e. roofing, painting, lighting, etc.) together with their remaining life, current cost, monthly reserve contribution, and net monthly allocation.

Detail Reports

The Detail Report itemizes each asset and lists all measurements, current and future costs, and calculations for that asset. Provisions for percentage replacements, salvage values, and one-time replacements can also be utilized. These reports can be sorted by category or group.

The numerical listings for each asset are enhanced by extensive narrative detailing factors such as design, manufactured quality, usage, exposure to elements and maintenance history.

The Detail Index is an alphabetical listing of all assets, together with the page number of the asset's detail report, the projected replacement year, and the asset number.

Projections

Thirty-year projections add to the usefulness of your reserve analysis study.

Definitions

Report I.D.

Includes the Report Date (example: November 15, 1992), Account Number (example: 9773), and Version (example: 1.0). Please use this information (displayed on the summary page) when referencing your report.

Budget Year Beginning/Ending

The budgetary year for which the report is prepared. For associations with fiscal years ending December 31st, the monthly contribution figures indicated are for the 12-month period beginning 1/1/20xx and ending 12/31/20xx.

Number of Units and/or Phases

If applicable, the number of units and/or phases included in this version of the report.

Inflation

This figure is used to approximate the future cost to repair or replace each component in the report. The current cost for each component is compounded on an annual basis by the number of remaining years to replacement, and the total is used in calculating the monthly reserve contribution that will be necessary to accumulate the required funds in time for replacement.

Annual Assessment Increase

This represents the percentage rate at which the association will increase its assessment to reserves at the end of each year. For example, in order to accumulate \$10,000 in 10 years, you could set aside \$1,000

per year. As an alternative, you could set aside \$795 the first year and increase that amount by 5% each year until the year of replacement. In either case you arrive at the same amount. The idea is that you start setting aside a lower amount and increase that number each year in accordance with the planned percentage. Ideally this figure should be equal to the rate of inflation. It can, however, be used to aide those associations that have not set aside appropriate reserves in the past, by making the initial year's allocation less formidable.

Investment Yield Before Taxes

The average interest rate anticipated by the association based upon its current investment practices.

Taxes on Interest Yield

The estimated percentage of interest income that will be set aside to pay income taxes on the interest earned.

Projected Reserve Balance

The anticipated reserve balance on the first day of the fiscal year for which this report has been prepared. This is based upon information provided and not audited.

Percent Fully Funded

The ratio, at the beginning of the fiscal year, of the actual (or projected) reserve balance to the calculated fully funded balance, expressed as a percentage.

Phase Increment Detail and/or Age

Comments regarding aging of the components on the basis of construction date or date of acceptance by the association.

Monthly Assessment

The assessment to reserves required by the association each month.

Interest Contribution (After Taxes)

The interest that should be earned on the reserves, net of taxes, based upon their beginning reserve balance and monthly contributions for one year. This figure is averaged for budgeting purposes.

Total Monthly Allocation

The sum of the monthly assessment and interest contribution figures.

Group and Category

The report may be prepared and sorted either by group (location, building, phase, etc.) or by category (roofing, painting, etc.). The standard report printing format is by category.

Percentage of Replacement or Repairs

In some cases, an asset may not be replaced in its entirety or the cost may be shared with a second party. Examples are budgeting for a percentage of replacement of streets over a period of time, or sharing the expense to replace a common wall with a neighboring party.

Placed-In-Service Date

The month and year that the asset was placed-in-service. This may be the construction date, the first escrow closure date in a given phase, or the date of the last servicing or replacement.

Estimated Useful Life

The estimated useful life of an asset based upon industry standards, manufacturer specifications, visual inspection, location, usage, association standards and prior history. All of these factors are taken into

consideration when tailoring the estimated useful life to the particular asset. For example, the carpeting in a hallway or elevator (a heavy traffic area) will not have the same life as the identical carpeting in a seldom-used meeting room or office.

Adjustment to Useful Life

Once the useful life is determined, it may be adjusted, up or down, by this separate figure for the current cycle of replacement. This will allow for a current period adjustment without affecting the estimated replacement cycles for future replacements.

Estimated Remaining Life

This calculation is completed internally based upon the report's fiscal year date and the date the asset was placed-in-service.

Replacement Year

The year that the asset is scheduled to be replaced. The appropriate funds will be available by the first day of the fiscal year for which replacement is anticipated.

Annual Fixed Reserves

An optional figure which, if used, will override the normal process of allocating reserves to each asset.

Fixed Assessment

An optional figure which, if used, will override all calculations and set the assessment at this amount. This assessment can be set for monthly, quarterly or annually as necessary.

Salvage Value

The salvage value of the asset at the time of replacement, if applicable.

One-Time Replacement

Notation if the asset is to be replaced on a one-time basis.

Current Replacement Cost

The estimated replacement cost effective at the beginning of the fiscal year for which the report is being prepared

Future Replacement Cost

The estimated cost to repair or replace the asset at the end of its estimated useful life based upon the current replacement cost and inflation.

Component Inventory

The task of selecting and qualifying reserve components. This task can be accomplished through on-site visual, review of association design and organizational documents, a review of established association precedents, and discussion with appropriate association representative(s).

A Multi-Purpose Tool

Your Report is an important part of your association's budgetary process. Following its recommendations should ensure the association's smooth budgetary transitions from one fiscal year to the next, and either decrease or eliminate the need for "special assessments".

In addition, your reserve study serves a variety of useful purposes:

- Following the recommendations of a reserve study performed by a professional consultant can protect the Board of Directors in a community from personal liability concerning reserve components and reserve funding.
- A reserve analysis study is required by your accountant during the preparation of the association's annual audit.
- The reserve study is often requested by lending institutions during the process of loan applications, both for the community and, in many cases, the individual owners.
- Your Report is also a detailed inventory of the association's major assets and serves as a management tool for scheduling, coordinating and planning future repairs and replacements.
- Your Report is a tool that can assist the Board in fulfilling its legal and fiduciary obligations for maintaining the community in a state of good repair. If a community is operating on a special assessment basis, it cannot guarantee that an assessment, when needed, will be passed. Therefore, it cannot guarantee its ability to perform the required repairs or replacements to those major components for which the association is obligated.
- Since the reserve analysis study includes measurements and cost estimates of the client's assets, the detail reports may be used to evaluate the accuracy and price of contractor bids when assets are due to be repaired or replaced.
- The reserve study is an annual disclosure to the membership concerning the financial condition of the association, and may be used as a "consumers' guide" by prospective purchasers.